



CXI3ZPY


report date: 2024-03-28

General information

Make	AUDI
Model	A8 TDI QUATTRO SPORT EXECUTIVE
Colour	Grey
Year of manufacture	2013
Top speed	155 mph
0 - 100 km/h	6.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	184 kW / 251 HP / 247 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 3

Date	2023-02-01
Pictures	7
Listing price	View report



JUNCTION 17	
Representative Example	
Monthly Payments	4.9%
Cash Price	£21,475.00
Deposit / Part Exchange	£2,000.00
Total Amount of Credit	£19,475.00
Interest Charge	£2,712.00
Credit Facility Fee	£0.00
Purchase Fee	£0.00
Total Cost of Credit	£2,712.00
Total Amount Payable	£22,187.00
Initial Payment	£200.00
Final Payment	£200.00
Duration of Agreement	60
Interest Rate Fixed	5.99%

source: cargurus.co.uk

Entry 2


Date	2023-01-31
Pictures	7
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-11-03
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-22
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	21
Total items failed	1

MOT #12	2024-02-19 15:13
MOT test number	230335704173
Result	✓ Passed
Next expiry date	2025-02-22
Advice	Rear Brake pad(s) wearing thin Inner pads look close to sensor (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2023-02-23 09:48
MOT test number	460142083972
Result	✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #10	2023-02-08 10:30
MOT test number	227075644322
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged outer sidewall damaged. (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged outer sidewall damaged. (5.2.3 (d) (ii))

**MOT #9** 2022-12-05 16:43**MOT test number** 498742604572**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear arm bush (5.3.4 (a) (i))**MOT #8** 2021-11-12 13:57**MOT test number** 477840805203**Result** ✓ Passed**MOT #7** 2020-12-05 12:27**MOT test number** 155845364748**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-12-03 15:16**MOT test number** 613513774230**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

**MOT #5** 2019-11-04 12:46**MOT test number** 786948543666**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-02-05 09:31**MOT test number** 901046068002**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-01-29 17:24**MOT test number** 686195421398**Result** ✓ Passed**MOT #2** 2017-02-20 09:14**MOT test number** 779040313743**Result** ✓ Passed**MOT #1** 2016-06-28 09:29**MOT test number** 578235681317**Result** ✓ Passed**Advice** Rear pads approx. 80% worn**Advice** Slight play in nearside inner steering rack joint



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-06-07
Last registration	2024-02-19
Complete history	See info



Registration #1	2013-06-07	10 mi
Registration #2	2016-06-28	30.038 mi
Registration #3	2017-02-20	35.475 mi
Registration #4	2018-01-29	42.739 mi
Registration #5	2019-02-05	54.602 mi
Registration #6	2019-11-04	62.026 mi
Registration #7	2020-12-03	71.836 mi
Registration #8	2020-12-05	71.868 mi
Registration #9	2021-01-20	75.277 mi
Registration #10	2021-03-20	75.277 mi
Registration #11	2021-05-20	75.277 mi
Registration #12	2021-07-20	75.277 mi
Registration #13	2021-09-20	75.277 mi
Registration #14	2021-11-20	75.277 mi
Registration #15	2022-01-20	75.277 mi
Registration #16	2022-03-20	75.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2111 mm
Height	1460 mm
Length	5137 mm
Wheel base	2992 mm
Kerb weight	1840 kg
Max. allowed weight	2530 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	CDTA015619