



TOYOTA

MT04KKR

report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Grey
Year of manufacture	2004
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	130 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-26
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-07
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	34
Total items failed	16

MOT #25	2024-04-08 13:21
MOT test number	867664432273
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #24	2024-04-08 11:36
MOT test number	727245782293
Result	✗ Failed
Fail	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor	Offside Front Tyre obviously under inflated (5.2.3 (l))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Both wipes loose REFITTED DONE
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #23**

2023-03-10 17:23

**MOT test number**

771494560845

**Result**

✓ Passed

**Advice**

Rear Exhaust heat shield corroded

**MOT #22**

2023-03-01 12:09

**MOT test number**

521438643480

**Result**

✗ Failed

**Advice**

Rear Exhaust heat shield corroded

**Fail**

Front Brakes imbalanced across an axle (1.2.1 (b) (i))

**MOT #21**

2022-03-05 16:47

**MOT test number**

908082860487

**Result**

✓ Passed

**Advice**

Rear Exhaust heat shield corroded

**MOT #20**

2021-03-03 17:26

**MOT test number**

912491646480

**Result**

✓ Passed

**Advice**

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice**

Nearside Front Coil spring corroded (5.3.1 (b) (i))

**Advice**

Central Rear Exhaust heat shield heavily deteriorating

**Advice**

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Offside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))

**MOT #19**

2021-03-03 09:14

**MOT test number**

977971185307

**Result****✗ Failed****Advice** Offside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Central Rear Exhaust heat shield heavily deteriorating**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #18**

2020-02-15 12:01

**MOT test number**

570467042489

**Result****✓ Passed****Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17** 2020-02-08 17:01**MOT test number** 247908116457**Result** ✗ Failed**Fail** Front Headlamp aim projected beam image is obviously incorrect both headlights (4.1.2 (c))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2019-02-19 09:13**MOT test number** 304964022565**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing Outer edge perished no cords visible (5.2.3 (d) (ii))**MOT #15** 2018-02-02 11:37**MOT test number** 435787800439**Result** ✓ Passed**MOT #14** 2017-03-02 16:34**MOT test number** 169237445689**Result** ✓ Passed**MOT #13** 2017-03-02 09:15**MOT test number** 932534040354**Result** ✗ Failed**Advice** O/s/f brake disc showing signs of overheat**Fail** Offside front brake binding (3.7.B.1)**Advice** O/s/f pad overheated and starting to crumble

**MOT #12** 2016-02-18 11:51**MOT test number** 976521561291**Result** ✓ Passed**MOT #11** 2016-02-17 09:43**MOT test number** 332232014338**Result** ✗ Failed**Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #10** 2015-02-02 11:41**MOT test number** 465643435071**Result** ✓ Passed**MOT #9** 2015-01-29 10:35**MOT test number** 945089925052**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #8** 2014-01-15 11:32**MOT test number** 737965914085**Result** ✓ Passed**MOT #7** 2013-01-11 10:12**MOT test number** 927411413099**Result** ✓ Passed



<b>MOT #6</b>	2012-01-11 11:48
---------------	------------------

<b>MOT test number</b>	928651812019
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2011-01-05 09:53
---------------	------------------

<b>MOT test number</b>	646625501096
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2010-01-05 15:56
---------------	------------------

<b>MOT test number</b>	560235700097
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2009-01-05 12:20
---------------	------------------

<b>MOT test number</b>	654585109030
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2008-01-14 16:03
---------------	------------------

<b>MOT test number</b>	900314918076
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2007-05-12 10:14
---------------	------------------

<b>MOT test number</b>	201842537190
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2004-05-12
Last registration	2024-04-08
Complete history	<a href="#">See info</a>



Registration #1	2004-05-12	12 mi
Registration #2	2007-05-12	17.463 mi
Registration #3	2008-01-14	19.892 mi
Registration #4	2009-01-05	28.596 mi
Registration #5	2010-01-05	37.367 mi
Registration #6	2011-01-05	41.454 mi
Registration #7	2012-01-11	44.285 mi
Registration #8	2013-01-11	48.472 mi
Registration #9	2014-01-15	53.284 mi
Registration #10	2015-01-29	58.361 mi
Registration #11	2015-02-02	58.361 mi
Registration #12	2016-02-17	61.125 mi
Registration #13	2016-02-18	61.125 mi
Registration #14	2017-03-02	63.799 mi
Registration #15	2018-03-20	65.377 mi
Registration #16	2019-03-20	65.377 mi
Registration #17	2020-03-20	65.377 mi
Registration #18	2021-03-20	65.377 mi
Registration #19	2022-03-20	65.377 mi
Registration #20	2023-03-20	65.377 mi
Registration #21	2024-03-20	65.377 mi
Registration #22	2025-03-20	65.377 mi
Registration #23	2026-03-20	65.377 mi
Registration #24	2027-03-20	65.377 mi
Registration #25	2028-03-20	65.377 mi
Registration #26	2029-03-20	65.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1130 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	4ZZU499329