



 **K60GKC**

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 SPORT LR P/V
Colour	Silver
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-01-31
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	18
Total items failed	35

MOT #13	2020-02-01 13:28
MOT test number	276337082163
Result	✓ Passed
Next expiry date	2021-01-31
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-01-27 17:22

MOT test number

160140667733

Result**✗ Failed**

- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Nearside Rear Leaf spring fractured (5.3.1 (b) (i))
- Fail** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Driver's seat insecure (6.2.5 (a) (ii))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Obligatory mirror does not provide a view to the rear (3.3 (c))
- Fail** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Fail** Offside Rear Leaf spring fractured (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

MOT #11

2018-08-03 13:49

MOT test number

928421387299

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Lower Suspension component mounting prescribed area damaged but not considered excessive shock absorber mounting bracket is distorted (5.3.6 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #10	2018-07-31 14:38
MOT test number	354599915174
Result	✗ Failed

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Seat belt missing (7.1.2 (a))

Fail Offside Front Windscreen washer not working (3.5 (a))

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced slam panel (6.1.1 (c) (i))

Fail Offside Rear Stop lamp(s) missing (4.3.1 (a) (ii))

Fail Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting door step (6.2.2 (d) (i))

Fail Offside Rear Direction indicator missing (4.4.1 (a) (ii))

Advice Offside Rear Lower Suspension component mounting prescribed area damaged but not considered excessive shock absorber mounting bracket is distorted (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Windscreen washer not working (3.5 (a))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced slam panel (6.1.1 (c) (i))

Fail Offside Rear Position lamp missing (4.2.1 (a))

Fail Offside Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill panel (6.2.2 (d) (i))

Fail Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting door step (6.2.2 (d) (i))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))



MOT #9	2018-03-23 12:37
MOT test number	546731724872
Result	✓ Passed
Advice	Corrosion on underside

MOT #8	2018-03-20 15:41
MOT test number	535017117563
Result	✗ Failed
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Front Headlamp not working on dipped beam (1.7.5a)
Advice	Corrosion on underside
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Stop lamp not working (1.2.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #7	2016-02-08 15:52
MOT test number	487245935328
Result	✓ Passed
Advice	Oil leak

MOT #6	2015-01-23 10:28
MOT test number	688453425070
Result	✓ Passed

MOT #5	2014-02-17 13:35
MOT test number	327898644032
Result	✓ Passed

**MOT #4** 2014-02-17 13:35**MOT test number** 607968644051**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2013-09-30 16:39**MOT test number** 239393073243**Result** ✓ Passed**Advice** Fuel hose slightly chafed (7.2.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #2** 2012-09-28 14:20**MOT test number** 396302172201**Result** ✓ Passed**MOT #1** 2011-10-03 09:29**MOT test number** 275636071232**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	K60GKC
Plate since	2019-03-28
Current registration	K60GKC
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-04-08
Last registration	2020-02-01
Complete history	See info



Registration #1	2008-04-08	26 mi
Registration #2	2011-10-03	59.021 mi
Registration #3	2012-09-28	78.012 mi
Registration #4	2013-09-30	91.641 mi
Registration #5	2014-02-17	95.043 mi
Registration #6	2015-01-23	188.444 mi
Registration #7	2016-02-08	192.354 mi
Registration #8	2016-02-08	192.354 mi
Registration #9	2016-02-08	192.354 mi
Registration #10	2016-02-08	192.354 mi
Registration #11	2016-02-08	192.354 mi
Registration #12	2016-02-08	192.354 mi
Registration #13	2016-02-08	192.354 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Height	2067 mm
Length	4863 mm
Wheel base	2933 mm
Kerb weight	1710 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	8Y32525