



Mercedes-Benz

PA54VLS

report date: 2024-03-28

General information

Make	MERCEDES
Model	VIANO CDI LONG AMBIENTE
Colour	Silver
Year of manufacture	2006
Top speed	108 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	329 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.1 mpg
CO2 emission	232 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-11-26
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-22
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	31
Total items failed	11

MOT #19	2023-12-06 09:08
MOT test number	538586675290
Result	✓ Passed
Next expiry date	2024-12-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer edge. (5.2.3 (e))

MOT #18	2022-12-23 16:39
MOT test number	962475105809
Result	✓ Passed
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17	2021-12-04 18:05
MOT test number	627313966647
Result	✓ Passed

MOT #16	2021-12-02 14:39
MOT test number	764151476647
Result	✗ Failed
MAJOR	Rear Seat belt missing (7.1.2 (a))

**MOT #15**

2020-11-28 20:38

MOT test number

364319758358

Result

✓ Passed

Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2020-11-28 20:38

MOT test number

360826988938

Result

✗ Failed

Pass with rectification Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Rear Other passenger door likely to open inadvertently or not remain closed (6.2.3 (b) (ii))**Pass with rectification** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Pass with rectification** Offside Rear Seat belt likely to become detached in the event of a collision (7.1.1 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Rear Seat belt anchorage loose (7.1.1 (b))

**MOT #13** 2019-05-10 12:49**MOT test number** 478503753187**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #12** 2018-04-19 15:38**MOT test number** 956922045941**Result** ✓ Passed**Advice** Rear Passenger seat(s) missing at time of test**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #11** 2018-04-19 15:38**MOT test number** 501717319057**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Rear Passenger seat(s) missing at time of test**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #10** 2017-05-06 08:21**MOT test number** 903960009712**Result** ✓ Passed**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Engine covers/undertrays**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #9** 2013-11-05 12:33**MOT test number** 337029203397**Result** ✓ Passed**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Offside rear seat slightly insecure.**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Notice** Slight damage to nearside front seatbelt attachment.**MOT #8** 2012-11-14 15:16**MOT test number** 946449112332**Result** ✓ Passed**MOT #7** 2011-10-06 15:59**MOT test number** 128619271247**Result** ✓ Passed**Notice** Front engine undertrays fitted**MOT #6** 2010-10-11 09:45**MOT test number** 833114780225**Result** ✓ Passed**MOT #5** 2010-04-19 14:22**MOT test number** 912369100155**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2010-04-19 14:22**MOT test number** 122229300102**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.5c)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2009-09-29 15:14**MOT test number** 614692279253**Result** ✓ Passed**MOT #2** 2008-09-25 13:33**MOT test number** 630969968217**Result** ✓ Passed**MOT #1** 2007-09-27 17:49**MOT test number** 311000977475**Result** ✓ Passed**Notice** Spare tyre missing**Notice** Nearside front tyre edge worn



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
22 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-07-14
Last registration	2023-12-06
Complete history	See info



Registration #1	2006-07-14	26 mi
Registration #2	2007-09-27	12.358 mi
Registration #3	2008-09-25	28.104 mi
Registration #4	2009-09-29	36.443 mi
Registration #5	2010-04-19	40.351 mi
Registration #6	2010-10-11	49.056 mi
Registration #7	2011-10-06	55.392 mi
Registration #8	2012-11-14	63.338 mi
Registration #9	2013-11-05	72.613 mi
Registration #10	2017-05-06	75.641 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi
Registration #18	2019-05-20	75.377 mi
Registration #19	2019-05-20	75.377 mi
Registration #20	2019-05-20	75.377 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1875 mm
Length	4993 mm
Wheel base	3200 mm
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	64698250198896