



report date: 2024-03-29

General information

Make	FIAT
Model	500 C POP
Colour	Blue
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 2


Date	2022-02-17
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-02-17
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	24
Total items failed	14

MOT #18	2024-01-31 11:01
MOT test number	592764213355
Result	✓ Passed
Next expiry date	2025-02-17
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #17	2024-01-30 09:22
MOT test number	513224714254
Result	✗ Failed
Fail	Exhaust has a major leak of exhaust gases front to rear (6.1.2 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Emissions unable to be completed (8.2.1.2 (d))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16	2023-02-02 16:25
MOT test number	289227711739
Result	✓ Passed

**MOT #15**

2023-02-02 08:58

**MOT test number**

550012067279

**Result****✗ Failed****Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #14**

2022-02-18 09:30

**MOT test number**

218431150627

**Result****✓ Passed****Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13**

2022-02-17 14:26

**MOT test number**

518476818455

**Result****✗ Failed****Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))**MOT #12**

2021-04-01 13:15

**MOT test number**

113124579973

**Result****✓ Passed**

**MOT #11** 2021-03-31 13:57**MOT test number** 702619919143**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #10** 2020-01-02 16:38**MOT test number** 379967425374**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both front +n/s/r (5.2.3 (e))**MOT #9** 2019-01-04 14:20**MOT test number** 478902938653**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**Minor** Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Advice** Both front upper strut top mountings have slight play

**MOT #8** 2019-01-04 10:35**MOT test number** 376147234380**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Central Rear Upper Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Both front upper strut top mountings have slight play
- Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))
- Advice** Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2018-01-03 10:25**MOT test number** 921330636755**Result** ✓ Passed

- Advice** Rear Upper Shock absorber has a slightly worn bush both sides (2.7.4)
- Advice** Centre box deteriorated slightly

**MOT #6** 2016-12-22 09:39**MOT test number** 871658828719**Result** ✓ Passed**MOT #5** 2015-12-22 15:01**MOT test number** 502281214085**Result** ✓ Passed

**MOT #4** 2015-12-22 15:01**MOT test number** 125170797391**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2014-12-22 12:36**MOT test number** 436116454462**Result** ✓ Passed**MOT #2** 2014-01-10 11:58**MOT test number** 108390314483**Result** ✓ Passed**MOT #1** 2014-01-09 12:55**MOT test number** 505229104084**Result** ✗ Failed**Fail** Offside Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Centre Stop lamp not working (1.2.1b)



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 May 2024

✓  
**MOT**

**Expires:**  
17 February 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	17 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-12-30
Last registration	2024-01-31
Complete history	<a href="#">See info</a>



Registration #1	2010-12-30	13 mi
Registration #2	2014-01-09	23.022 mi
Registration #3	2014-01-10	23.022 mi
Registration #4	2014-12-22	29.464 mi
Registration #5	2015-12-22	38.789 mi
Registration #6	2015-12-22	38.789 mi
Registration #7	2016-12-22	45.945 mi
Registration #8	2018-01-03	51.064 mi
Registration #9	2019-01-04	56.045 mi
Registration #10	2019-01-04	56.045 mi
Registration #11	2019-01-04	56.045 mi
Registration #12	2019-01-04	56.045 mi
Registration #13	2019-01-04	56.045 mi
Registration #14	2019-01-04	56.045 mi
Registration #15	2019-01-04	56.045 mi
Registration #16	2019-01-04	56.045 mi
Registration #17	2019-01-04	56.045 mi
Registration #18	2019-01-04	56.045 mi
Registration #19	2019-01-04	56.045 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	0002281