




General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	White
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-10-09
Pictures	51
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-08
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	18
Total items failed	0

MOT #12	2023-10-03 13:47
MOT test number	664684592439
Result	✓ Passed
Next expiry date	2024-10-26

MOT #11	2023-10-03 09:07
MOT test number	559055476079
Result	✗ Failed
MAJOR	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
MAJOR	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Undertray not fully secure (8.1.1 (b) (i))

MOT #10	2022-10-03 09:05
MOT test number	826281146653
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2022-10-03 07:38**MOT test number** 675444987178**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #8** 2021-10-27 07:04**MOT test number** 335310088092**Result** ✓ Passed**MOT #7** 2021-07-12 11:08**MOT test number** 291339516672**Result** ✓ Passed**MOT #6** 2021-07-09 13:49**MOT test number** 414982311317**Result** ✗ Failed**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #5** 2020-09-16 08:24**MOT test number** 767780665938**Result** ✓ Passed

**MOT #4** 2020-09-08 08:42**MOT test number** 570405672794**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))**MAJOR** Horn not working (7.7 (a) (ii))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #3** 2019-09-05 14:36**MOT test number** 474053272549**Result** ✓ Passed**MOT #2** 2019-08-30 10:57**MOT test number** 794208861865**Result** ✗ Failed**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2018-08-30 16:05**MOT test number** 795458096630**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GN65XHW
Plate since	2019-06-29
Current registration	 GN65XHW
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-09-10
Last registration	2023-10-03
Complete history	See info



Registration #1	2015-09-10	9 mi
Registration #2	2018-08-30	26.319 mi
Registration #3	2019-08-30	35.254 mi
Registration #4	2019-09-05	35.254 mi
Registration #5	2020-09-08	44.323 mi
Registration #6	2020-09-16	44.513 mi
Registration #7	2021-07-09	48.514 mi
Registration #8	2021-07-12	48.514 mi
Registration #9	2022-05-20	55.277 mi
Registration #10	2022-05-20	55.277 mi
Registration #11	2022-05-20	55.277 mi
Registration #12	2022-05-20	55.277 mi
Registration #13	2022-05-20	55.277 mi
Registration #14	2022-05-20	55.277 mi
Registration #15	2022-05-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CHYA451626