



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | MAZDA          |
| Model               | 5 TAKUYA       |
| Colour              | Grey           |
| Year of manufacture | 2012           |
| Top speed           | 134 mph        |
| 0 - 60 mph          | 10.3 seconds   |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 155 BHP             |
| Max. torque             | 193 Nm at 4.500 rpm |
| Engine capacity         | 1.999 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 29.4 mpg            |
| Consumption extra urban | 53.3 mpg            |
| Consumption combined    | 40.9 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-04-24                  |
| Pictures      | 14                          |
| Listing price | <a href="#">View report</a> |



source: yesauto.com

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2024-05-16 |
| <b>MOT pass rate</b>      | 75 %       |
| <b>MOT passed</b>         | 9          |
| <b>Failed MOT tests</b>   | 3          |
| <b>Total advice items</b> | 25         |
| <b>Total items failed</b> | 3          |

|                         |  |
|-------------------------|--|
| <b>MOT #12</b>          | 2023-05-16 12:09   |
| <b>MOT test number</b>  | 795103409426   |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2024-05-16   |
| <b>Advice</b>           | Rear Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a)) |
| <b>Advice</b>           | N/s/f tyre sidewall slightly damaged (run on under pressure)       |

|                        |  |
|------------------------|--|
| <b>MOT #11</b>         | 2023-05-15 15:06   |
| <b>MOT test number</b> | 409484559019   |
| <b>Result</b>          | ✗ Failed   |
| <b>Advice</b>          | Rear Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a)) |
| <b>Advice</b>          | N/s/f tyre sidewall slightly damaged (run on under pressure)       |
| <b>Fail</b>            | Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))  |

|                        |                  |
|------------------------|------------------|
| <b>MOT #10</b>         | 2022-05-17 15:09 |
| <b>MOT test number</b> | 763434027817     |
| <b>Result</b>          | ✓ Passed         |

**MOT #9** 2022-05-17 15:09**MOT test number** 816779595416**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8** 2021-09-27 09:52**MOT test number** 374086022464**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Centre heatshield slightly insecure**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #7** 2020-09-30 10:41**MOT test number** 215961321323**Result** ✓ Passed**Advice** Engine oil level low**MOT #6** 2019-09-26 15:14**MOT test number** 391049855288**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #5** 2018-09-26 14:11**MOT test number** 905362408384**Result** ✓ Passed

**MOT #4**

2017-09-19 11:54

**MOT test number**

568996527135

**Result**

✓ Passed

**Advice**

Both rear tyres splitting in the tread and the offside rear tyre worn on inner edge

**MOT #3**

2016-09-23 15:11

**MOT test number**

514818623185

**Result**

✓ Passed

**Advice**

Offside Rear tyre perished and worn on inner edge

**Advice**

Cant inspect rear seatbelts

**MOT #2**

2015-09-29 14:41

**MOT test number**

746013270316

**Result**

✓ Passed

**Advice**

Rear brake pads 50% wear low

**Advice**

Sill covers fitted

**Advice**

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Under trays fitted

**Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Both front tyres slightly cracked (No cord)

**Advice**

Front brake fluctuating, but not excessively also have slight brake imbalance (3.7.B.3)



MOT #12015-09-29 09:11

MOT test number261898329541

| Result |   | ✗ Failed |
|--------|---|----------|
| Advice | Under trays fitted  |          |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1)                             |          |
| Advice | Front brake fluctuating, but not excessively also have slight brake imbalance (3.7.B.3) |          |
| Advice | Rear brake pads 50% wear low  |          |
| Fail   | Offside Rear Shock absorber has a serious fluid leak (2.7.3)                            |          |
| Advice | Sill covers fitted  |          |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1)                              |          |



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
16 May 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Valid until 1 May               |
| Days left        | 366                             |
| MOT expiry date  | 16 May 2024                     |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 14                       |
| First mileage registration | 2012-09-28               |
| Last registration          | 2023-05-16               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-09-28 | 18 mi     |
| Registration #2  | 2015-09-29 | 19.601 mi |
| Registration #3  | 2015-09-29 | 19.601 mi |
| Registration #4  | 2016-09-23 | 24.681 mi |
| Registration #5  | 2017-09-19 | 29.118 mi |
| Registration #6  | 2018-09-26 | 32.648 mi |
| Registration #7  | 2019-09-26 | 36.025 mi |
| Registration #8  | 2020-05-20 | 38.277 mi |
| Registration #9  | 2021-05-20 | 39.277 mi |
| Registration #10 | 2022-05-20 | 40.277 mi |
| Registration #11 | 2023-05-16 | 41.277 mi |
| Registration #12 | 2024-03-28 | 42.277 mi |
| Registration #13 | 2024-03-28 | 43.277 mi |
| Registration #14 | 2024-03-28 | 44.277 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 77%                             |
| Children       | 81%                             |
| Pedestrian     | 49%                             |
| Safety systems | 71%                             |
| Overall rating | 72%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1795 mm |
| Height              | 1440 mm |
| Length              | 4755 mm |
| Wheel base          | 2725 mm |
| Kerb weight         | 1435 kg |
| Max. allowed weight | 1955 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 64 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Number of axles    | 2                     |
| Engine number      | LF 20409679           |