



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	1007 SPORT
Colour	Grey
Year of manufacture	2006
Top speed	103 mph
0 - 60 mph	17.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-15
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-09-24
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	26
Total items failed	15

MOT #24 2022-09-24 16:00

MOT test number 471464918587

Result ✓ Passed

Next expiry date 2023-09-24

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear EXHAUST BOX CORRODED AND MINOR LEAK

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23 2022-09-24 15:26

MOT test number 185046926508

Result ✗ Failed

Advice Rear EXHAUST BOX CORRODED AND MINOR LEAK

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #22** 2021-09-25 16:45**MOT test number** 834665780001**Result** ✓ Passed**MOT #21** 2020-11-16 11:45**MOT test number** 655676425949**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #20** 2019-11-07 14:53**MOT test number** 858884135176**Result** ✓ Passed**MOT #19** 2019-11-07 10:46**MOT test number** 329947391988**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #18** 2018-11-21 15:26**MOT test number** 978760558991**Result** ✓ Passed**MOT #17** 2018-11-21 15:26**MOT test number** 248455999461**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #16** 2017-10-05 13:30**MOT test number** 476828751172**Result** ✓ Passed**MOT #15** 2017-10-04 10:57**MOT test number** 626960130555**Result** ✗ Failed**Fail** Front Anti-roll bar linkage has excessive play in a pin/bearing (2.4.G.2)**Fail** Nearside Front Front drive shaft coupling flexible rubber or fabric coupling unit breaking up (2.5.C.1d)**MOT #14** 2016-10-06 09:47**MOT test number** 915160220466**Result** ✓ Passed**MOT #13** 2015-10-07 12:45**MOT test number** 597844569706**Result** ✓ Passed**MOT #12** 2015-10-07 12:45**MOT test number** 811470910287**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #11** 2014-10-03 14:17**MOT test number** 318176074221**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Rear exhaust box slightly deteriorated**Notice** Nearside sunvisor can not be stowed in the off screen position

**MOT #10**

2014-10-01 11:18

MOT test number

945284574251

Result**✗ Failed**

- Notice** Offside wiper blade ends split
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Nearside sunvisor can not be stowed in the off screen position
- Notice** Nearside wiper blade ends split
- Fail** Horn not working (1.6.2a)
- Notice** Rear exhaust box slightly deteriorated

MOT #9

2013-10-02 15:12

MOT test number

329695173205

Result**✓ Passed****MOT #8**

2013-10-02 12:01

MOT test number

355285273426

Result**✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside Stop lamp not working (1.2.1b)

MOT #7

2012-10-09 12:02

MOT test number

666023782246

Result**✓ Passed**

- Notice** Rear exhaust box slightly deteriorated
- Notice** Nearside sunvisor does not stay in the up position

**MOT #6** 2011-10-07 12:15**MOT test number** 326330681288**Result** ✓ Passed**Notice** Nearside sunvisor will not stay in the up position**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #5** 2010-09-29 12:29**MOT test number** 882622670225**Result** ✓ Passed**MOT #4** 2010-09-29 10:35**MOT test number** 303482970219**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** FRONT WIPER BLADES SPLIT**MOT #3** 2009-10-02 16:27**MOT test number** 201645879259**Result** ✓ Passed**MOT #2** 2009-01-30 13:26**MOT test number** 144360939430**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1 2009-01-30 11:37

MOT test number 184690139494

Result ✗ Failed

- Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
24 September 2023

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	GL55SYC
Plate since	2024-03-28
Current registration	GL55SYC
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-01-30
Last registration	2022-09-24
Complete history	See info



Registration #1	2006-01-30	14 mi
Registration #2	2009-01-30	25.912 mi
Registration #3	2009-01-30	25.912 mi
Registration #4	2009-10-02	30.013 mi
Registration #5	2010-09-29	30.495 mi
Registration #6	2010-09-29	30.495 mi
Registration #7	2011-10-07	31.386 mi
Registration #8	2012-10-09	31.972 mi
Registration #9	2013-10-02	33.059 mi
Registration #10	2013-10-02	33.059 mi
Registration #11	2014-10-01	33.553 mi
Registration #12	2014-10-03	33.553 mi
Registration #13	2015-10-07	35.422 mi
Registration #14	2016-10-07	36.313 mi
Registration #15	2017-10-07	37.204 mi
Registration #16	2018-10-07	38.095 mi
Registration #17	2019-10-07	38.986 mi
Registration #18	2020-10-07	39.877 mi
Registration #19	2021-10-07	40.768 mi
Registration #20	2022-09-24	41.659 mi
Registration #21	2022-09-24	41.659 mi
Registration #22	2022-09-24	41.659 mi
Registration #23	2022-09-24	41.659 mi
Registration #24	2022-09-24	41.659 mi
Registration #25	2022-09-24	41.659 mi
Registration #26	2022-09-24	41.659 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1662 mm
Height	1610 mm
Length	3731 mm
Wheel base	2315 mm
Kerb weight	1145 kg
Max. allowed weight	1559 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	FSV25212275