



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GTE ADVANCE DSG
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 100 km/h	7.6 seconds
0 - 60 mph	7.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	115 kW / 157 HP / 215 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	166.2 mpg
CO2 emission	40 g/km
CO2 label	A





Internet history

Entry 2


Date	2022-02-28
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2022-02-03
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	24
Total items failed	0

MOT #5 2024-01-24 14:02

MOT test number 343152062884

Result ✓ Passed

Next expiry date 2025-01-23

- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords inner side wall (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #4 2023-01-18 09:42

MOT test number 781983428864

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both N/S and O/S discs corroded (1.1.14 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin Both N/S and O/S inner and outer pads worn to 2mm (1.1.13 (a) (ii))
- Advice** Central Rear Exhaust mounting defective Heat shield above back box clips corroded (6.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both N/S and O/S discs corroded (1.1.14 (a) (ii))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view Scratch on screen (3.2 (a) (i))

**MOT #3** 2022-01-24 10:21**MOT test number** 359322827971**Result** ✓ Passed**MOT #2** 2021-07-01 15:53**MOT test number** 178883958847**Result** ✓ Passed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3/3/2mm (5.2.3 (e))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Under trays fitted obscuring some underside components
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3/2/3mm (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #1 2021-07-01 09:05**MOT test number** 352335618194**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3/3/2mm (5.2.3 (e))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 2/2/1mm (5.2.3 (e))
- Advice** Under trays fitted obscuring some underside components
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3/2/3mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3/2/2mm (5.2.3 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BC18HDA
Plate since	2019-06-29
Current registration	 BC18HDA
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-07-12
Last registration	2024-01-24
Complete history	See info



Registration #1	2018-07-12	24 mi
Registration #2	2021-07-01	34.393 mi
Registration #3	2021-07-01	34.393 mi
Registration #4	2022-01-24	42.796 mi
Registration #5	2023-01-24	51.199 mi
Registration #6	2023-01-24	51.199 mi
Registration #7	2023-01-24	51.199 mi
Registration #8	2024-01-24	59.602 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1477 mm
Length	4767 mm
Wheel base	2791 mm
Kerb weight	1660 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CUKC118668