



report date: 2024-03-28

General information

Make	FORD
Model	KA KA STYLE
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #15</b>	2020-08-07 09:41
<b>MOT test number</b>	930829196382
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-08-06
<b>Advice</b> Offside Front Lower Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))	
<b>Advice</b> Nearside Front Lower Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))	
<b>Advice</b> Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

<b>MOT #14</b>	2019-08-07 14:29
<b>MOT test number</b>	321754470863
<b>Result</b>	✓ Passed
<b>Advice</b> Oil leak, but not excessive (8.4.1 (a) (i))	
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

<b>MOT #13</b>	2019-08-01 15:35
<b>MOT test number</b>	423398724860
<b>Result</b>	✗ Failed
<b>Fail</b> Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))	
<b>Fail</b> Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))	
<b>Fail</b> Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
<b>Advice</b> Oil leak, but not excessive (8.4.1 (a) (i))	
<b>Advice</b> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Fail</b> Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))	

**MOT #12**

2018-04-26 14:43

**MOT test number**

146193129684

**Result**

✓ Passed

**Advice** Nearside rear wing corroded around fuel filler**Advice** Offside rear tyre worn**MOT #11**

2018-04-26 10:48

**MOT test number**

128348023461

**Result**

✗ Failed

**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement inner rear bush (2.4.G.2)**Advice** Offside rear tyre worn**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement inner rear bush (2.4.G.2)**Advice** Nearside rear wing corroded around fuel filler**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #10**

2017-04-24 12:14

**MOT test number**

141392405913

**Result**

✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)

**MOT #9** 2016-05-04 10:43**MOT test number** 237752925169**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
Rear bush (2.4.G.2)**Advice** Offside front tyre worn on inner edge**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside rear tyre perished**MOT #8** 2015-05-07 09:49**MOT test number** 288507725493**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nearside rear tyre sidewall perished**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-05-07 09:31**MOT test number** 288087624449**Result** ✓ Passed**MOT #6** 2013-05-09 11:21**MOT test number** 685489123189**Result** ✓ Passed**MOT #5** 2012-04-26 15:12**MOT test number** 797557812166**Result** ✓ Passed

**MOT #4** 2012-04-24 10:15**MOT test number** 188445712147**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Play in steering rack inner joint(s)**Fail** Nearside Power steering component(s) leaking from a failed seal (2.3.3b)**MOT #3** 2011-05-11 09:37**MOT test number** 978141031125**Result** ✓ Passed**MOT #2** 2011-05-11 09:37**MOT test number** 446281631159**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #1** 2010-03-05 17:13**MOT test number** 350234360086**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-03-22
Last registration	2020-08-07
Complete history	<a href="#">See info</a>



Registration #1	2007-03-22	24 mi
Registration #2	2010-03-05	15.760 mi
Registration #3	2011-05-11	22.788 mi
Registration #4	2012-04-24	25.359 mi
Registration #5	2012-04-26	25.428 mi
Registration #6	2013-05-09	33.105 mi
Registration #7	2014-05-07	40.330 mi
Registration #8	2015-05-07	45.480 mi
Registration #9	2016-05-07	50.530 mi
Registration #10	2017-05-07	55.580 mi
Registration #11	2018-05-07	60.630 mi
Registration #12	2019-05-07	65.680 mi
Registration #13	2020-05-07	70.730 mi
Registration #14	2021-05-07	75.780 mi
Registration #15	2022-05-07	80.830 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	898 kg
Max. allowed weight	1265 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	7Y71081