




report date: 2024-03-28

General information

Make	FIAT
Model	SCUDO COMFORT P/V MULTIJET
Colour	White
Year of manufacture	2013
Top speed	90 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	40.9 mpg
CO2 emission	182 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-08
Pictures	40
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-20
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #10 2023-09-13 10:02

MOT test number 132699152813

Result ✓ Passed

Next expiry date 2024-09-20

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Coolant leak

MOT #9 2022-09-21 14:28

MOT test number 946935154370

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8** 2021-09-17 16:50**MOT test number** 870721561920**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-09-17 16:50**MOT test number** 797058867098**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))**MOT #6** 2020-12-04 08:54**MOT test number** 110534899127**Result** ✓ Passed

**MOT #5** 2019-06-03 09:25**MOT test number** 879115216684**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #4** 2018-06-11 15:36**MOT test number** 213270948455**Result** ✓ Passed**MOT #3** 2017-11-17 09:52**MOT test number** 544565718854**Result** ✓ Passed**MOT #2** 2016-11-18 15:00**MOT test number** 527844597647**Result** ✓ Passed**MOT #1** 2016-11-17 09:41**MOT test number** 452685094755**Result** ✗ Failed**Fail** Central Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 September 2024

Tax status		Valid until 1 September
Days left		125
MOT expiry date		20 September 2024
Full MOT history		See MOT history

Tax calculation


Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	CV63FKK
Plate since	2019-09-28
Current registration	CV63FKK
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-29
Last registration	2023-09-13
Complete history	See info



Registration #1	2013-11-29	27 mi
Registration #2	2016-11-17	15.906 mi
Registration #3	2016-11-18	15.933 mi
Registration #4	2017-11-17	36.059 mi
Registration #5	2018-06-11	43.018 mi
Registration #6	2019-06-03	55.385 mi
Registration #7	2019-06-03	55.385 mi
Registration #8	2019-06-03	55.385 mi
Registration #9	2019-06-03	55.385 mi
Registration #10	2019-06-03	55.385 mi
Registration #11	2019-06-03	55.385 mi
Registration #12	2019-06-03	55.385 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	0023330