





report date: 2024-03-28

### General information

Make	RENAULT
Model	TRAFIC LL29 DCI 115 PV LWB LC
Colour	White
Year of manufacture	2013
Top speed	99 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
<b>Engine capacity</b>	1.996 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	ı



CarCheck.co.uk page 1/11



## Internet history

### Entry 1

Date 2022-05-26

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #9	2023-05-11 11:57
MOT test number	199428677274
Result	✓ Passed
Next expiry date	2024-05-18

MOI #8	2023-04-27 13:25
MOT test number	299872839447
Result	<b>×</b> Failed
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #7	2022-05-19 11:54
MOT test number	387546201185
Result	<b>✓</b> Passed
Advice Play in steering rack inner joint(s)	

MOT #6		2020-12-03 16:04
MOT test	number	422450852747
Result		✓ Passed
Advice	Nearside Play in steering rack inner joint(s)	
Advice	O/s/r trailing arm front bush unbonding	

CarCheck.co.uk page 3/11



MOT #5 2019-06-05 15:12

MOT test number 895159585573

**Result** 
✓ Passed

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement o/s trailing arm front bush unbonding (5.3.4 (a) (i))

**Advice** Nearside Play in steering rack inner joint(s)

**Advice** Front pads low

MOT #4 2019-06-05 15:12

MOT test number 880213211963

**Result** X Failed

Advice Rear Sub-frame pin or bush worn but not resulting in excessive movement o/s trailing arm front bush unbonding (5.3.4 (a) (i))

**Advice** Nearside Play in steering rack inner joint(s)

**Advice** Front pads low

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #3 2018-05-15 12:24

MOT test number 516610725964

Advice Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement o/s front bush unbonded (2.4.G.2)

**MOT #2** 2017-05-24 12:25

MOT test number 619756480424

Result 

Passed

**Advice** N/s/r tyre close to the limit

MOT #1 2016-05-05 13:49

MOT test number 150278333141

Result 

Passed

CarCheck.co.uk page 4/11





Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	18 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union matery	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
	More info >
Plate changes  See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	UK UK
Flate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-05-24
Last registration	2023-05-11
Complete history	See info



Registration #1	2013-05-24	24 mi
Registration #2	2016-05-05	38.684 mi
Registration #3	2017-05-24	52.171 mi
Registration #4	2018-05-15	65.906 mi
Registration #5	2019-06-05	78.512 mi
Registration #6	2019-06-05	78.512 mi
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 es
Registration #10		0.074
Registration #11		10.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



# Dimensions & weight

Width	1904 mm
Height	1962 mm
Length	5182 mm
Max. allowed weight	3030 kg

## Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C102129

CarCheck.co.uk page 11/11