



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Black
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G





MOT history

MOT expiry date	2024-03-07
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	20
Total items failed	30

MOT #18	2023-03-08 16:14
MOT test number	357507844933
Result	✓ Passed
Next expiry date	2024-03-07
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Parking brake lever worn, but not excessively (1.1.6 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	REAR box exhaust deteriorated
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2023-03-07 14:10

**MOT test number**

405684046225

**Result****✗ Failed**

**Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt GEAR (6.1.7 (g) (ii))

**Advice** Parking brake lever worn, but not excessively (1.1.6 (b) (i))

**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Side repeater not working (4.4.1 (a) (ii))

**Advice** REAR box exhaust deteriorated

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #16**

2022-02-26 11:26

**MOT test number**

676876857826

**Result****✓ Passed****MOT #15**

2022-02-26 10:15

**MOT test number**

542762491781

**Result****✗ Failed**

**Fail** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

**MOT #14** 2021-03-06 13:20**MOT test number** 253185473211**Result** ✓ Passed**Advice** Age related surface rust under vehicle**Advice** Front Sub-frame pin or bush worn but not resulting in excessive movement rear both sides (5.3.4 (a) (i))**MOT #13** 2020-07-15 12:23**MOT test number** 797903780569**Result** ✓ Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #12** 2019-07-23 13:45**MOT test number** 326349536795**Result** ✓ Passed**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2019-07-23 12:53**MOT test number** 326754205936**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10** 2018-01-09 12:57**MOT test number** 414792645051**Result** ✓ Passed**MOT #9** 2017-02-04 11:28**MOT test number** 190646997555**Result** ✓ Passed**MOT #8** 2016-02-08 11:14**MOT test number** 312518307321**Result** ✓ Passed**MOT #7** 2016-02-06 10:00**MOT test number** 924411199073**Result** ✗ Failed

- Fail** Offside Rear Rear fog lamp not working not working (1.3.2b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Headlamp insecure headlamp bulb insecure (1.7.3)
- Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)
- Fail** Nearside Front Headlamp insecure headlamp bulbs insecure (1.7.3)

**MOT #6** 2015-02-04 17:00**MOT test number** 628875535065**Result** ✓ Passed

**MOT #5**

2015-02-03 17:04

**MOT test number**

635564335040

**Result****✗ Failed**

- Fail** Nearside Headlamp aim not tested (1.8.A.1c)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)
- Fail** Nearside Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Rear Wheel bolt(s) missing (4.2.A.1e)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Headlamp aim not tested (1.8.A.1c)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Front registration plate deteriorated (6.3.1d)
- Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Nearside Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #4**

2014-01-18 10:45

**MOT test number**

639958514053

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-01-26 09:57
MOT test number	857726423019
Result	✓ Passed
<div>NoticeWipers smearing</div>	

MOT #2	2012-01-11 09:06
MOT test number	248131412004
Result	✓ Passed

MOT #1	2011-01-26 14:38
MOT test number	337366821089
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
29 February 2024

X

MOT

Expired:  
7 March 2024

Tax status	Expired at 29 February 2024
Days left	61 days too late
MOT expiry date	7 March 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LN08ZZM</b>
Plate since	2024-03-29
Current registration	<b>LN08ZZM</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-13
Last registration	2023-03-08
Complete history	<a href="#">See info</a>



Registration #1	2008-03-13	12 mi
Registration #2	2011-01-26	6.137 mi
Registration #3	2012-01-11	7.814 mi
Registration #4	2013-01-26	24.099 mi
Registration #5	2014-01-18	35.859 mi
Registration #6	2015-02-03	53.640 mi
Registration #7	2015-02-04	53.640 mi
Registration #8	2016-02-06	71.413 mi
Registration #9	2016-02-08	71.518 mi
Registration #10	2017-02-04	80.527 mi
Registration #11	2018-03-29	95.337 mi
Registration #12	2019-03-29	101.337 mi
Registration #13	2020-03-29	107.337 mi
Registration #14	2021-03-29	113.337 mi
Registration #15	2022-03-29	119.337 mi
Registration #16	2023-03-29	125.337 mi
Registration #17	2024-03-29	131.337 mi
Registration #18	2025-03-29	137.337 mi
Registration #19	2026-03-29	143.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

BUD524379