



E008PZX

report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM TDCI 125
Colour	Silver
Year of manufacture	-
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg




LABEL UNKNOWN



Internet history


Entry 2

Date	2021-11-20
Pictures	1
Listing price	View report



Video viewing
Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.


[Visit our website for more info](#)



source: [cargurus.co.uk](#)


Entry 1

Date	2021-06-11
Pictures	1
Listing price	View report



Video viewing
Book a video viewing with one of our team.
See the vehicle from the comfort of your own home.

[Visit our website for more info](#)



source: [autotrader.co.uk](#)



MOT history

MOT #18	2022-01-24 11:23
MOT test number	736104082788
Result	✓ Passed
Next expiry date	2023-01-23
Advice	Front Both front shock absorbers corroded at the bottom
Advice	Sub-frame corroded but not seriously weakened Both front and rear (5.3.3 (b) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Lower Suspension arm corroded but not seriously weakened Both sides (5.3.3 (b) (i))

MOT #17	2021-06-10 11:29
MOT test number	681209087872
Result	✓ Passed
Advice	Rear Tyre slightly damaged/cracking or perishing both cracking in treads (5.2.3 (d) (ii))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2021-06-10 11:29
MOT test number	819374935649
Result	✗ Failed
Advice	Rear Tyre slightly damaged/cracking or perishing both cracking in treads (5.2.3 (d) (ii))
Pass with rectification	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Pass with rectification	Horn not working (7.7 (a) (ii))

**MOT #15** 2020-10-15 08:27**MOT test number** 248080411460**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14** 2019-11-25 11:36**MOT test number** 968735128816**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Both front tyres slightly worn on inner edges**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Windscreen chipped**MOT #13** 2018-11-14 14:16**MOT test number** 276181958870**Result** ✓ Passed**MOT #12** 2017-11-24 12:00**MOT test number** 936026786401**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2017-11-24 12:00**MOT test number** 236778872233**Result** ✗ Failed**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2016-11-11 08:53

MOT test number

559490482015

Result

✓ Passed

Advice Nearside Rear Trailing arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9**

2015-11-24 10:04

MOT test number

589972832403

Result

✓ Passed

Advice Rear Exhaust corroded**MOT #8**

2014-12-02 09:16

MOT test number

275926634372

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**MOT #7**

2013-04-30 11:04

MOT test number

329070823138

Result

✓ Passed

**MOT #6** 2013-04-30 11:04**MOT test number** 238190723401**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator not working (1.4.A.2c)**MOT #5** 2012-05-04 17:54**MOT test number** 689975822176**Result** ✓ Passed**MOT #4** 2012-03-30 09:19**MOT test number** 739630092078**Result** ✓ Passed**Advice** Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2012-03-30 09:19**MOT test number** 665280292035**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2011-02-23 11:20**MOT test number** 845904551027**Result** ✓ Passed



MOT #1	2011-02-23 08:40
MOT test number	135894451413
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Fail	Nearside Stop lamp not working (1.2.1b)
Pass with rectification	Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-20
Last registration	2022-01-24
Complete history	See info



Registration #1	2008-03-20	8 mi
Registration #2	2011-02-23	47.359 mi
Registration #3	2011-02-23	47.359 mi
Registration #4	2012-03-30	60.277 mi
Registration #5	2012-05-04	60.527 mi
Registration #6	2013-04-30	81.592 mi
Registration #7	2014-12-02	103.581 mi
Registration #8	2015-11-24	104.462 mi
Registration #9	2016-11-11	106.991 mi
Registration #10	2016-11-11	106.991 mi
Registration #11	2016-11-11	106.991 mi
Registration #12	2016-11-11	106.991 mi
Registration #13	2016-11-11	106.991 mi
Registration #14	2016-11-11	106.991 mi
Registration #15	2016-11-11	106.991 mi
Registration #16	2016-11-11	106.991 mi
Registration #17	2016-11-11	106.991 mi
Registration #18	2016-11-11	106.991 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	8L51488