



report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D2 CROSS COUNTRY LUX
Colour	Red
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-14
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	27
Total items failed	6

MOT #11	2024-04-15 11:26
---------	------------------

MOT test number	742980557001
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-04-14
------------------	------------

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Wearing inner edge unevenly and close to 1.6mm limit (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge badly and close to 1.6mm limit (5.2.3 (e))

**MOT #10**

2024-04-09 08:39

MOT test number

824250979099

Result

✗ Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing inner edge (5.2.3 (e))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt Insecure (2.1.3 (g) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing inner edge badly and close to 1.6mm limit (5.2.3 (e))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt Insecure (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Wearing inner edge unevenly and close to 1.6mm limit (5.2.3 (e))**MOT #9**

2023-04-05 10:18

MOT test number

804313491641

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view Slight damage in various areas (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Wearing inner edge and nail in tread (5.2.3 (e))**MOT #8**

2022-04-04 09:13

MOT test number

341833490726

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2021-04-09 14:41

MOT test number

434491741207

Result

✓ Passed

**MOT #6** 2020-02-26 12:32**MOT test number** 204502959077**Result** ✓ Passed**MOT #5** 2019-03-06 10:38**MOT test number** 193705428706**Result** ✓ Passed**MOT #4** 2018-03-09 16:37**MOT test number** 707403021257**Result** ✓ Passed**Advice** Nearside Front tyre sidewall damaged**MOT #3** 2018-02-28 14:20**MOT test number** 970971622582**Result** ✗ Failed**Advice** Nearside Front tyre sidewall damaged**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2 2017-03-01 09:42

MOT test number 907040273499

Result ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Nail in tyre

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2017-03-01 09:42

MOT test number 394333020270

Result ✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Nail in tyre

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	WJ14MVO
Plate since	2019-09-28
Current registration	WJ14MVO
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-03
Last registration	2024-04-15
Complete history	See info



Registration #1	2014-03-03	13 mi
Registration #2	2017-03-01	72.222 mi
Registration #3	2017-03-01	72.222 mi
Registration #4	2018-02-28	82.366 mi
Registration #5	2018-03-09	82.633 mi
Registration #6	2019-03-06	93.459 mi
Registration #7	2020-02-26	104.522 mi
Registration #8	2020-03-27	115.577 mi
Registration #9	2020-03-27	115.577 mi
Registration #10	2020-03-27	115.577 mi
Registration #11	2020-03-27	115.577 mi
Registration #12	2020-03-27	115.577 mi
Registration #13	2020-03-27	115.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1783 mm
Height	1458 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1472 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2723939