





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA ZETEC TDCI
Colour	Blue
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	47.9 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-30

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



RV100ET report date: 2024-03-28

MOT history

MOT expiry date	2025-04-04
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #15	2024-04-05 09:20
MOT test number	985467830088
Result	✓ Passed
Next expiry date	2025-04-04
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1	
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #14	2023-03-29	09:33
MOT test i	number 6643941	92873
Result	√ P	Passed
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Front Tyre worn close to legal limit/worn on edge Nearside and Offside, edge(s) (5.2.3 (e))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13		2022-03-23 10:39
MOT test	number	272179815659
Result		✓ Passed
Advice	Undertray not fully secure (8.1.1 (b) (i))	
Advice	Oil leak, but not excessive From Engine Sump (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (b) (i))	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn Offside	& Nearside (5.1.2

MOT #12	2021-04-29 08:48
MOT test number	631217128739
Result	✓ Passed
MOT #11	2019-08-01 14:32
MOT to at number	125524020046

MOT test number

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))

Minor Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

489156215717

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge ON LIMIT (5.2.3 (e))

Fail Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

Advice Offside Front Suspension arm ball joint has slight play ON LIMIT (5.3.4 (a) (i))

choice the caspendent sampener has single play on an in (cite that (a)	
MOT #9	2018-08-11 10:55
MOT test number	115492582175
Result	✓ Passed
MOT #8	2017-08-07 11:01
MOT test number	760395335889
Result	✓ Passed
MOT #7	2016-08-16 13:58
MOT test number	985358987004
Result	✓ Passed
MOT #6	2016-02-03 10:41
MOT test number	830727704127
Result	✓ Passed
Advice All tyres worn	

MOT #5	2015-02-16 10:49
MOT test number	856387145087
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3

MOT test number

Result

Notice Oil leak

Notice Damage to offside front inner wing panel

 MOT #2
 2014-03-22 12:22

 MOT test number
 307541084088

 Result
 ✓ Passed

 MOT #1
 2013-03-07 10:44

 MOT test number
 349906563023

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



RV100ET report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



RV100ET report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-16
Last registration	2024-04-05
Complete history	See info



Registration #1	2010-03-16	9 mi
Registration #2	2013-03-07	27.816 mi
Registration #3	2014-03-22	31.642 mi
Registration #4	2014-08-14	34.705 mi
Registration #5	2015-02-16	35.564 mi
Registration #6	2016-02-03	51.405 mi
Registration #7	2016-08-16	59.134 mi
Registration #8	2017-08-07	68.084 mi
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		11.777 es

More info >

page 12/13 CarCheck.co.uk



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1155 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

9E23153