



RENAULT



report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------|
| Make | RENAULT |
| Model | MASTER LM35 LWB L/C P/V 120 |
| Colour | White |
| Year of manufacture | 2009 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 120 BHP |
| Max. torque | 300 Nm at 1.600 rpm |
| Engine capacity | 2.464 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 26.4 mpg |
| Consumption extra urban | 36.2 mpg |
| Consumption combined | 36.2 mpg |



LABEL UNKNOWN



Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-06-18 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-01 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-03 |
| MOT pass rate | 63 % |
| MOT passed | 10 |
| Failed MOT tests | 6 |
| Total advice items | 38 |
| Total items failed | 37 |

| | |
|------------------|--|
| MOT #16 | 2023-10-19 12:54 |
| MOT test number | 575790608865 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-03 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|--|
| MOT #15 | 2022-11-01 15:11 |
| MOT test number | 526457722134 |
| Result | ✓ Passed |
| Advice | Nearside Rear Nail in tyre |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #14**

2022-10-25 08:03

MOT test number

184808694750

Result**✗ Failed**

- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Nail in tyre
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Exhaust system insecure (6.1.2 (a))



MOT #13

2021-11-04 16:17

MOT test number

106543175893

Result

✓ Passed

- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Fluid leak, but not excessive (8.4.1 (a) (i))
- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Exhaust bracket missing but exhaust is still secure
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2021-09-21 13:46

MOT test number

528958918061

Result**✗ Failed**

Fail Brake performance not tested Brake disc significantly and obviously worn Brake fluid contaminated (1.2.1 (g))

Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Floor excessively deteriorated Driverside (6.2.4 (a) (i))

Fail Front Brake disc significantly and obviously worn Both side (1.1.14 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

Fail Brake fluid contaminated (1.8 (a))

Fail Horn sound not in accordance with requirements (7.7 (c))

Minor Nearside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Brake pedal wearing smooth (1.1.2 (c))

Fail Exhaust system insecure (6.1.2 (a))

Advice Fuel pipe on the engine is corroded

Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))

Fail Offside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

MOT #11

2019-07-23 14:45

MOT test number

515266822520

Result**✓ Passed**

Advice Brake pedal rubber worn

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice Exhaust mounting defective (6.1.2 (a))

**MOT #10**

2019-07-17 11:58

MOT test number

473377243907

Result

✗ Failed

Minor

Power steering fluid level below minimum (2.1.5 (b) (i))

Fail

Offside Side repeater not working (4.4.1 (a) (ii))

Fail

Power steering malfunctioning (2.1.5 (a))

Advice

Exhaust mounting defective (6.1.2 (a))

Fail

Offside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))

Advice

Power steering pipe/hose has slight seepage (2.1.5 (a))

Advice

Brake pedal rubber worn

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail

Nearside Rear Tyre has ply or cords exposed on tread (5.2.3 (d) (ii))

Fail

Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #9

2018-06-07 13:33

MOT test number

535745026344

Result

✓ Passed

MOT #8

2017-02-02 17:54

MOT test number

146619701427

Result

✓ Passed

MOT #7

2015-12-17 17:46

MOT test number

366382997016

Result

✓ Passed

Advice

Brake pedal rubber worn

**MOT #6** 2014-08-15 13:38**MOT test number** 457587924232**Result** ✓ Passed**MOT #5** 2014-08-15 10:09**MOT test number** 546957124296**Result** ✗ Failed**Fail** Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front Direction indicators not working (1.4.A.2c)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2013-05-28 16:18**MOT test number** 638868043145**Result** ✓ Passed**MOT #3** 2013-05-17 17:49**MOT test number** 555667533177**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Power steering fluid level below minimum (2.3.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)



MOT #2 2012-02-13 13:54

MOT test number 575844042094

Result ✓ Passed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #1 2012-02-13 13:54

MOT test number 105924742406

Result ✗ Failed

Advice Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Pass with rectification Offside Front Headlamp aim too high (1.8)

Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
3 November 2024

| | |
|-------------------|------------------------|
| Tax status | Valid until 1 February |
|-------------------|------------------------|

| | |
|------------------|-----|
| Days left | 277 |
|------------------|-----|

| | |
|------------------------|-----------------|
| MOT expiry date | 3 November 2024 |
|------------------------|-----------------|

| | |
|-------------------------|---------------------------------|
| Full MOT history | See MOT history |
|-------------------------|---------------------------------|



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  ***** |
| Plate since | 2019-09-29 |
| Current registration |  ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2009-03-03 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-03-03 | 18 mi |
| Registration #2 | 2012-02-13 | 57.554 mi |
| Registration #3 | 2013-05-17 | 71.455 mi |
| Registration #4 | 2013-05-28 | 71.456 mi |
| Registration #5 | 2014-08-15 | 76.102 mi |
| Registration #6 | 2014-08-15 | 76.102 mi |
| Registration #7 | 2015-12-17 | 96.370 mi |
| Registration #8 | 2017-02-02 | 108.399 mi |
| Registration #9 | 2018-06-07 | 119.413 mi |
| Registration #10 | 2019-06-20 | 131.377 mi |
| Registration #11 | 2019-06-20 | 131.377 mi |
| Registration #12 | 2019-06-20 | 131.377 mi |
| Registration #13 | 2019-06-20 | 131.377 mi |
| Registration #14 | 2019-06-20 | 131.377 mi |
| Registration #15 | 2019-06-20 | 131.377 mi |
| Registration #16 | 2019-06-20 | 131.377 mi |
| Registration #17 | 2019-06-20 | 131.377 mi |
| Registration #18 | 2019-06-20 | 131.377 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1990 mm |
| Height | 2489 mm |
| Length | 5388 mm |
| Wheel base | 4078 mm |
| Kerb weight | 1937 kg |
| Max. allowed weight | 3500 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 100 l |
| Fuel delivery | Direct Injection |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | C122702 |