



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Black
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





## MOT history

MOT expiry date	2020-11-08
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	25
Total items failed	9

MOT #10 2019-05-09 11:08

MOT test number 487413017968

Result ✓ Passed

Next expiry date 2020-11-08

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2018-05-03 08:23

MOT test number 617578207373

Result ✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #8** 2018-05-02 13:48**MOT test number** 386477717725**Result** ✗ Failed**Fail** Offside Rear Stop lamp emits other than a steady red light lens broken (1.2.1e)**Advice** Nearside Rear Nail in tyre**Fail** Offside Rear Rear position lamp(s) incorrect colour lens broken (1.1.A.3e)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2017-04-21 16:17**MOT test number** 788462067891**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2016-05-05 14:22**MOT test number** 274181319587**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Inner Wear on tyre tread**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-05-05 14:22**MOT test number** 320850044040**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Inner Wear on tyre tread**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4** 2015-04-30 17:38**MOT test number** 568160925165**Result** ✓ Passed**MOT #3** 2015-04-30 12:19**MOT test number** 449180725165**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Nail in offside rear tyre**Advice** Nearside Outer Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Outer Rear position lamp(s) not working (1.1.A.3b)**Notice** Nail in nearside rear tyre**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Inner Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-04-30 09:10**MOT test number** 708000324118**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-04-09 17:02
MOT test number	319139693042
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 July 2021

✕  
MOT

Expired:  
8 November 2020

Tax status	Expired at 1 July 2021
Days left	1034 days too late
MOT expiry date	8 November 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>BN10UVG</b>
Plate since	2024-03-29
Current registration	 <b>BN10UVG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-05-08
Last registration	2019-05-09
Complete history	<a href="#">See info</a>



Registration #1	2010-05-08	27 mi
Registration #2	2013-04-09	51.218 mi
Registration #3	2014-04-30	65.225 mi
Registration #4	2015-04-30	81.935 mi
Registration #5	2015-04-30	81.935 mi
Registration #6	2016-05-05	102.040 mi
Registration #7	2019-05-09	102.040 mi
Registration #8	2019-05-09	102.040 mi
Registration #9	2019-05-09	102.040 mi
Registration #10	2019-05-09	102.040 mi
Registration #11	2019-05-09	102.040 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	CAY 211766