





report date: 2024-03-28

# General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Blue
Year of manufacture	-
Top speed	138 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	110 BHP	
Max. torque	240 Nm at 1.750 rpm	
Cylinders	4	
Fuel type	Diesel	
Consumption city	38.7 mpg	
Consumption extra urban	60.1 mpg	
Consumption combined	50.4 mpg	



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

# Entry 1


Date 2021-06-27


Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

2024-02-16

### **MOT** history

Next expiry date

MOT #16	2023-02-02 15:25
MOT test number	887180140920

**MOT #15** 2023-02-02 09:30

**MOT test number** 701096536706

**Result** X Failed

**DANGEROUS** Offside Front Inner Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #14 2022-02-17 10:03
MOT test number 912329136246

**Result** ✓ Passed

**MOT #13** 2021-03-18 10:05

**MOT test number** 863490728012

**Result** ✓ Passed

**MOT #12** 2021-03-12 11:38

**MOT test number** 830040856419

**Result** X Failed

**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #11		2020-03-19 09:15
MOT test no	umber	211338220424
Result		✓ Passed
MOT #10		2019-03-20 12:57
MOT test no	umber	385936010607
Result		✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #9		2018-03-12 11:38
MOT test	number	318841284654
Result		<b>✓</b> Passed
MOT #8		2017-03-14 12:20
MOT test	number	431354336079
Result		✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #7	2016-03-14 11:40
MOT test number	818876321934
Result	<b>✓</b> Passed
MOT #6	2015-03-21 13:02
MOT test number	858480785025
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

258238575025

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Rear brake disc in such a condition that it is seriously weakened (3.5.1i)


MOT #4 2014-05-30 14:54 **MOT** test number 497330254186 Result Passed **Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Parking brake lever has little reserve travel (3.1.6b)

MOT #3	2013-05-31 15:41
MOT test number	157751253174
Result	✓ Passed
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)  Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/12



report date: 2024-03-28



2011-06-09 10:19
537990461121
✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

factor scincore

KO08ABV

report date: 2024-03-28

# For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

See in this check if this CITROEN had different number plates.

More info >

CarCheck.co.uk page 9/12



KOO8ABV report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-06-30
Last registration	2023-02-02
Complete history	See info



Registration #1	2008-06-30	19 mi
Registration #2	2011-06-09	33.450 mi
Registration #3	2012-05-31	41.931 mi
Registration #4	2013-05-31	55.564 mi
Registration #5	2014-05-30	69.362 mi
Registration #6	2015-03-19	79.037 mi
Registration #7	2015-03-21	79.037 mi
Registration #8	2016-03-14	88.873 mi
Registration #9	2017-03-14	98.751 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Safety ratings

NCAP rating	****	0
-------------	------	---

**Video** <u>see crash video</u>

# Dimensions & weight

Width	1853 mm
Height	1456 mm
Length	4779 mm
Wheel base	2815 mm
Max. allowed weight	2040 kg

# Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBAJ3106942

CarCheck.co.uk page 12/12