



RENAULT



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | RENAULT |
| Model | KANGOO AUTHENTIQUE 16V E4 |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 101 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 95 BHP |
| Max. torque | 148 Nm at 3.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.7 mpg |
| Consumption extra urban | 44.8 mpg |
| Consumption combined | 35.3 mpg |
| CO2 emission | 190 g/km |
| CO2 label | J |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2023-08-03 |
| Pictures | 18 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-08 |
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #15 | 2023-06-09 06:39 |
| MOT test number | 197189138203 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-08 |

| | |
|-----------------|---|
| MOT #14 | 2023-06-05 15:26 |
| MOT test number | 830132132872 |
| Result | ✗ Failed |
| Minor | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) |
| Fail | Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) |



| | |
|----------------|------------------|
| MOT #13 | 2022-10-07 11:39 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 195739501174 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | All 4 tyres have slight cracks between tread |
|---------------|--|

| | |
|--------------|--|
| Minor | Front Windscreen wiper blade defective both fronts (3.4 (b) (i)) |
|--------------|--|

| | |
|---------------|---|
| Advice | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) |
|---------------|---|

| | |
|---------------|-------------------------------------|
| Advice | Offside exhaust tail pipe corroding |
|---------------|-------------------------------------|

| | |
|---------------|--|
| Advice | Rear under body rear dry rusty condition |
|---------------|--|

| | |
|----------------|------------------|
| MOT #12 | 2021-11-19 09:27 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 203275477599 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|----------------|------------------|
| MOT #11 | 2020-11-02 09:18 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 126118047233 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|----------------|------------------|
| MOT #10 | 2019-10-31 09:06 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 617951113927 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #9 | 2018-10-31 11:20 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 395505493513 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #8 | 2017-10-27 09:57 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 570820903231 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

**MOT #7** 2016-11-03 14:28**MOT test number** 358592151694**Result** ✓ Passed**MOT #6** 2015-09-03 14:24**MOT test number** 284972974181**Result** ✓ Passed**MOT #5** 2015-09-02 00:00**MOT test number** 675478315574**Result** ✗ Failed**Fail** Nearside Rear Brake hose excessively chafed (3.6.B.4d)**MOT #4** 2014-09-02 14:42**MOT test number** 368365244292**Result** ✓ Passed**MOT #3** 2013-11-04 12:42**MOT test number** 819568403385**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Front tyres getting low 3.0mm**MOT #2** 2012-11-26 13:11**MOT test number** 166181732333**Result** ✓ Passed**Notice** Both front tyres getting low 3.0mm



| | |
|-----------------|------------------|
| MOT #1 | 2012-01-24 15:04 |
| MOT test number | 785884322027 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 8 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | |
|-------------------|-----------------|
| Finance company | RENAULT FINANCE |
| Date of agreement | 2024-03-28 |
| Agreement type | RENT TO BUY |
| Agreement term | 36 months |
| Agreement number | 123456789 |
| Contact info | 01234 567890 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-03-01 |
| Last registration | 2023-06-09 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-03-01 | 21 mi |
| Registration #2 | 2012-01-24 | 12.511 mi |
| Registration #3 | 2012-11-26 | 15.808 mi |
| Registration #4 | 2013-11-04 | 18.973 mi |
| Registration #5 | 2014-09-02 | 20.182 mi |
| Registration #6 | 2015-09-02 | 22.992 mi |
| Registration #7 | 2015-09-03 | 22.992 mi |
| Registration #8 | 2016-11-03 | 26.100 mi |
| Registration #9 | 2017-10-27 | 27.454 mi |
| Registration #10 | 2018-06-20 | 28.377 mi |
| Registration #11 | 2019-06-20 | 29.377 mi |
| Registration #12 | 2020-06-20 | 30.377 mi |
| Registration #13 | 2021-06-20 | 31.377 mi |
| Registration #14 | 2022-06-20 | 32.377 mi |
| Registration #15 | 2023-06-20 | 33.377 mi |
| Registration #16 | 2024-06-20 | 34.377 mi |
| Registration #17 | 2025-06-20 | 35.377 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1672 mm |
| Height | 1855 mm |
| Length | 4035 mm |
| Wheel base | 2605 mm |
| Max. allowed weight | 1645 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

Engine number

D024579