



PEUGEOT



KD54NZF


report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 D TURBO HDI (110BHP)
Colour	Silver
Year of manufacture	2004
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.3 mpg
Consumption extra urban	67.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-08
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-26
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	41
Total items failed	15

MOT #22	2023-05-27 10:21
MOT test number	765531960950
Result	✓ Passed
Next expiry date	2024-05-26
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #21**

2023-05-19 15:02

MOT test number

485204035760

Result**✗ Failed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Emissions unable to be completed (8.2.2.2 (e))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #20

2022-03-18 15:26

MOT test number

164384135443

Result**✓ Passed**

- Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement bush cracking (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both n/s o/s (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-03-15 09:21

MOT test number

266244737955

Result

✗ Failed

Fail Nearside Rear Outer Suspension arm pin or bush excessively worn stabbliser arm bush (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both n/s o/s (1.1.14 (a) (ii))**Fail** Offside Rear Outer Suspension arm pin or bush excessively worn stabbliser bush worn (5.3.4 (a) (i))**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement bush cracking (5.3.4 (a) (i))**MOT #18**

2021-03-20 09:51

MOT test number

101399968451

Result

✓ Passed

Advice Brake discs and pads**MOT #17**

2020-06-02 14:11

MOT test number

647921412338

Result

✓ Passed

Advice N/s front drop link worn front brake discs corroded and pads low front tyres on limit 1.6 mm front inner wishbone bushes perished**MOT #16**

2019-05-10 13:55

MOT test number

875148883637

Result

✓ Passed

Advice Front brake discs corroded

**MOT #15** 2018-05-08 15:45**MOT test number** 371344203454**Result** ✓ Passed**Advice** Both front tyres**Advice** Brake pipes corroded**Advice** O/s front spring corroded**MOT #14** 2017-05-12 12:36**MOT test number** 333186267207**Result** ✓ Passed**MOT #13** 2017-05-09 13:20**MOT test number** 147472331329**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #12** 2016-06-16 12:22**MOT test number** 633988206731**Result** ✓ Passed**Advice** Slight play in o/s bottom ball joint**MOT #11** 2015-06-25 10:26**MOT test number** 347836475131**Result** ✓ Passed**Notice** Exhaust corroded

**MOT #10** 2014-06-19 15:18**MOT test number** 708240474129**Result** ✓ Passed**Notice** Wipers worn**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Notice** Rear exhaust corroded**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2013-06-11 13:33**MOT test number** 437722263190**Result** ✓ Passed**Notice** N/s rear lower shocker bush worn**Notice** Exhaust corroded**Notice** Rear radius arm bushes worn**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2012-06-29 11:40**MOT test number** 227341382176**Result** ✓ Passed**Notice** Wipers worn**MOT #7** 2011-06-06 11:44**MOT test number** 425837151127**Result** ✓ Passed

**MOT #6** 2010-06-07 11:48**MOT test number** 203548650151**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-06-09 16:06**MOT test number** 240800469421**Result** ✓ Passed**MOT #4** 2009-06-09 10:09**MOT test number** 543850769175**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Registration plate lamp not working (1.1.5c)**MOT #3** 2008-06-12 09:58**MOT test number** 483144268189**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-06-12 09:58**MOT test number** 834304168120**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Rear Stop lamp excessively damaged so that it is not visible from a reasonable distance (1.2.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2007-10-08 13:47
MOT test number	102771487274
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
26 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	26 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KD54NZF
Plate since	2024-03-29
Current registration	KD54NZF
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-11-05
Last registration	2023-05-27
Complete history	See info



Registration #1	2004-11-05	20 mi
Registration #2	2007-10-08	38.506 mi
Registration #3	2008-06-12	43.538 mi
Registration #4	2009-06-09	48.280 mi
Registration #5	2009-06-09	48.281 mi
Registration #6	2010-06-07	52.962 mi
Registration #7	2011-06-06	56.227 mi
Registration #8	2012-06-29	65.493 mi
Registration #9	2013-06-11	76.006 mi
Registration #10	2014-06-19	87.151 mi
Registration #11	2015-06-25	98.626 mi
Registration #12	2016-06-16	112.115 mi
Registration #13	2016-06-16	112.115 mi
Registration #14	2016-06-16	112.115 mi
Registration #15	2016-06-16	112.115 mi
Registration #16	2016-06-16	112.115 mi
Registration #17	2016-06-16	112.115 mi
Registration #18	2016-06-16	112.115 mi
Registration #19	2016-06-16	112.115 mi
Registration #20	2016-06-16	112.115 mi
Registration #21	2016-06-16	112.115 mi
Registration #22	2016-06-16	112.115 mi
Registration #23	2016-06-16	112.115 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1279 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Engine number	DYPS4008262