



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	CLK CLK230 KOMPRESSOR ELEGANCE
Colour	Blue
Year of manufacture	-
Top speed	143 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	38.7 mpg
Consumption combined	28.5 mpg





Internet history

Entry 1

Date	2021-08-02
Pictures	4
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #22	2022-03-03 14:44
MOT test number	526049450445
Result	✓ Passed
Next expiry date	2023-03-02

MOT #21	2022-03-03 08:44
MOT test number	487161196119
Result	✗ Failed

Fail Brake pipe excessively corroded both front to rear (1.1.11 (c))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

MOT #20	2020-12-10 16:15
MOT test number	460652261316
Result	✓ Passed

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing close to legal limit (5.2.3 (e))

MOT #19	2020-12-02 17:38
MOT test number	706351674537
Result	✗ Failed

Fail Nearside Headlamp lens seriously defective (4.1.1 (b) (ii))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing close to legal limit (5.2.3 (e))

Fail Rear fog lamp switch inoperative (4.5.3 (a) (ii))

Fail Offside Headlamp lens seriously defective (4.1.1 (b) (ii))

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #182019-06-21 15:16

MOT test number164827705446

Result

✓ Passed

- Advice

Headlights poor images
- Advice

Sill covers and undertrays fitted
- Advice

Nearside and offside front tyres worn on inside edges
- Advice

Nearside and offside front to rear metal brake pipes corroded
- Advice

Child seat fitted to rear
- Advice

Wiper blade split
- Advice

Offside rear wheel arch corroded
- Advice

Nearside and offside front anti roll bar outer bushes worn
- Advice

Engine management light on

**MOT #17**

2019-06-21 13:19

MOT test number

191989134500

Result**✗ Failed**

- Advice** Sill covers and undertrays fitted
- Advice** Child seat fitted to rear
- Advice** Nearside and offside front tyres worn on inside edges
- Advice** Nearside and offside front to rear metal brake pipes corroded
- Advice** Wiper blade split
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords in tread (5.2.3 (d) (i))
- Advice** Engine management light on
- Advice** Offside rear wheel arch corroded
- Advice** Headlights poor images
- Advice** Nearside and offside front anti roll bar outer bushes worn
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16

2018-06-29 11:37

MOT test number

252245164953

Result**✓ Passed**

- Advice** Nearside and offside rear flexi hoses perished
- Advice** Offside rear wheel arch corroded
- Advice** Offside rear tyre worn
- Advice** Sill covers and undertrays fitted
- Advice** Nail in nearside rear tyre and worn

**MOT #15**

2018-06-26 11:18

MOT test number

138731913103

Result**✗ Failed****Advice** Sill covers and undertrays fitted**Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Nail in nearside rear tyre and worn**Advice** Nearside and offside rear flexi hoses perished**Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))**Advice** Offside rear wheel arch corroded**Advice** Offside rear tyre worn**MOT #14**

2017-06-19 11:32

MOT test number

491004874678

Result**✓ Passed****Advice** Child seats fitted rear**Advice** Undertrays fitted**Advice** O/s rear wheel arch rusty**Advice** N/s and o/s front tyres inner edges perished**Advice** Siil covers fitted**Advice** N/s and o/s rear flexi brake pipes perished

**MOT #13**

2017-05-30 15:44

MOT test number

893477114165

Result**✗ Failed****Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Nearside and offside rear flexis perished**Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front rear brake excessively fluctuating (3.7.B.3)**Advice** Sill covers fitted**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Offside rear wheel arch corroded**Fail** Registration plate lamp shows direct white light to the rear (1.1.C.1f)**Advice** Nearside and offside front tyres worn**Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Nearside rear brake excessively fluctuating (3.7.B.3)**Advice** Child seat fitted to offside rear**Advice** Undertrays fitted**MOT #12**

2016-06-23 16:08

MOT test number

983603977149

Result**✓ Passed****Advice** Front prop coupling perished



MOT #11

2015-06-20 11:16

MOT test number

798551175121

Result

✓ Passed

- Notice

Under-trays fitted obscuring some underside components
- Notice

Gearbox leaking oil
- Advice

Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Notice

Sill covers fitted
- Notice

Nearside and offside rear flexi hoses perished
- Notice

Nearside and offside rear tyres worn low
- Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Notice

Engine management light on

**MOT #10**

2014-06-30 10:31

MOT test number

938291884187

Result

✓ Passed

- Notice** Nearside and offside rear flexis perished
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Notice** Play in steering
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Front exhaust mountng missing
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Notice** Nail in nearside rear tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brakes slight fluctuation
- Notice** Sill covers fitted
- Notice** Centre exhaust mounting broken

MOT #9

2013-07-01 11:41

MOT test number

299302083152

Result

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)
- Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2012-06-07 16:51**MOT test number** 757739352145**Result** ✓ Passed**MOT #7** 2012-06-07 16:20**MOT test number** 867559152172**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2011-06-02 14:27**MOT test number** 219283151107**Result** ✓ Passed**MOT #5** 2010-06-09 17:22**MOT test number** 262250060454**Result** ✓ Passed**MOT #4** 2009-07-07 11:38**MOT test number** 803848489187**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Rear brake pads low**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Notice** Front brake pads low**Notice** Both front tyres worn on edges



MOT #3	2008-06-18 10:41
MOT test number	981280478126
Result	✓ Passed
Advice	Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #2	2007-07-10 09:41
MOT test number	940721397103
Result	✓ Passed

MOT #1	2006-07-10 12:57
MOT test number	441191196187
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-06-24
Last registration	2022-03-03
Complete history	See info



Registration #1	2003-06-24	17 mi
Registration #2	2006-07-10	64.737 mi
Registration #3	2007-07-10	72.507 mi
Registration #4	2008-06-18	80.130 mi
Registration #5	2009-07-07	88.464 mi
Registration #6	2010-06-09	94.519 mi
Registration #7	2011-06-02	99.321 mi
Registration #8	2012-06-07	105.836 mi
Registration #9	2012-06-07	105.836 mi
Registration #10	2013-07-01	112.960 mi
Registration #11	2014-06-30	120.352 mi
Registration #12	2015-06-20	126.356 mi
Registration #13	2016-06-20	132.360 mi
Registration #14	2017-06-20	138.364 mi
Registration #15	2018-06-20	144.368 mi
Registration #16	2019-06-20	150.372 mi
Registration #17	2020-06-20	156.376 mi
Registration #18	2021-06-20	162.380 mi
Registration #19	2022-03-03	168.384 mi
Registration #20	2023-03-03	174.388 mi
Registration #21	2024-03-03	180.392 mi
Registration #22	2025-03-03	186.396 mi
Registration #23	2026-03-03	192.400 mi
Registration #24	2027-03-03	198.404 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1727 mm
Height	1346 mm
Length	4572 mm
Wheel base	2690 mm
Kerb weight	1645 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198232466340