



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE S
Colour	Blue
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	143 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-05
Pictures	3
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #19	2023-07-26 14:31
MOT test number	718650810903
Result	✓ Passed
Next expiry date	2024-07-28
Minor	Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #18	2023-07-21 12:12
MOT test number	373925201574
Result	✗ Failed
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Minor	Nearside Front Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #17**

2022-07-29 08:46

MOT test number

408254995914

Result

✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #16

2022-07-22 13:25

MOT test number

959868537457

Result

✗ Failed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))



MOT #15	2021-07-07 12:45
----------------	------------------

MOT test number	391113011534
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #14	2020-11-04 09:36
----------------	------------------

MOT test number	329407755596
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2019-05-08 09:57
----------------	------------------

MOT test number	159675204713
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2018-08-24 10:46
----------------	------------------

MOT test number	653251772938
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear exhaust rear flange has corrosion
---------------	--

Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
---------------	--

Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
---------------	---

**MOT #11**

2018-08-21 08:28

MOT test number

552830475403

Result

✗ Failed

- Minor** Offside Front Brake hose slightly damaged brake ferules corroded (1.1.12 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Minor** Nearside Rear Brake hose slightly damaged ferules corroded (1.1.12 (b) (i))
- Minor** Nearside Front Brake hose slightly damaged brake ferules corroded (1.1.12 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Rear exhaust rear flange has corrosion
- Minor** Offside Rear Brake hose slightly damaged brake ferules corroded (1.1.12 (b) (i))

MOT #10

2017-08-21 16:05

MOT test number

315110664230

Result

✓ Passed

MOT #9

2016-08-26 13:00

MOT test number

785984136607

Result

✓ Passed

MOT #8

2015-08-21 13:25

MOT test number

630292347082

Result

✓ Passed



MOT #7	2014-09-11 08:11
MOT test number	447124254227
Result	✓ Passed
MOT #6	2013-09-04 15:22
MOT test number	289427043281
Result	✓ Passed
MOT #5	2012-09-13 15:14
MOT test number	785477552297
Result	✓ Passed
MOT #4	2011-09-14 10:50
MOT test number	355537751476
Result	✓ Passed
MOT #3	2011-09-14 10:50
MOT test number	317937551467
Result	✗ Failed
<div>Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)</div> <div>Pass with rectification Nearside Headlamp aim too low (1.8)</div>	
MOT #2	2010-08-23 07:41
MOT test number	474325430222
Result	✓ Passed
MOT #1	2009-08-27 10:11
MOT test number	353399139221
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-01
Last registration	2023-07-26
Complete history	See info



Registration #1	2006-09-01	29 mi
Registration #2	2009-08-27	10.981 mi
Registration #3	2010-08-23	14.393 mi
Registration #4	2011-09-14	18.506 mi
Registration #5	2012-09-13	21.479 mi
Registration #6	2013-09-04	24.253 mi
Registration #7	2014-09-11	26.193 mi
Registration #8	2015-08-21	27.598 mi
Registration #9	2016-08-26	29.435 mi
Registration #10	2017-08-21	30.753 mi
Registration #11	2018-08-21	31.377 mi
Registration #12	2019-08-21	32.377 mi
Registration #13	2020-08-21	33.377 mi
Registration #14	2021-08-21	34.377 mi
Registration #15	2022-08-21	35.377 mi
Registration #16	2023-08-21	36.377 mi
Registration #17	2024-08-21	37.377 mi
Registration #18	2025-08-21	38.377 mi
Registration #19	2026-08-21	39.377 mi
Registration #20	2027-08-21	40.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1332 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED6382478