



MF06BSZ

report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Gold
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 3

Date	2021-11-06
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 2

Date	2021-09-30
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-23
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2021-10-02
-----------------	------------

MOT pass rate	93 %
---------------	------

MOT passed	13
------------	----

Failed MOT tests	1
------------------	---

Total advice items	45
--------------------	----

Total items failed	0
--------------------	---

MOT #14	2020-10-03 13:07
---------	------------------

MOT test number	695922711510
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-10-02
------------------	------------

Advice	Corrosion under-vehicle in places
--------	-----------------------------------

Advice	Oil leak, but not excessive (8.4.1 (a) (i))
--------	---

Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
--------	--

Advice	Wipers slightly smearing
--------	--------------------------

Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
-------	---

Advice	Front and rear suspension components corroded
--------	---

Advice	Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
--------	--

Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	--

Advice	Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
--------	---

Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
-------	---

Advice	Fuel filter insecure
--------	----------------------



MOT #13	2020-09-12 11:04
MOT test number	226292283347
Result	✗ Failed

MAJOR Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Wipers slightly smearing

DANGEROUS Exhaust emits excessive smoke or vapour likely to obscure the vision of other road users (8.2.2.2 (c))

MAJOR Nearside Front Road wheel fixing missing wheel nut (5.2.1 (a) (i))

MAJOR Front Registration plate incorrect incorrect spacing (0.1 (c))

Advice Front and rear suspension components corroded

MAJOR Nearside Rear Road wheel fixing missing wheel nut (5.2.1 (a) (i))

MAJOR Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MAJOR Exhaust has a major leak of exhaust gases front pipe (6.1.2 (a))

Advice Nearside Front Nail in tyre

MAJOR Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))

MAJOR Offside Rear Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

MAJOR Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Advice Fuel filter insecure

MAJOR Offside Front Road wheel fixing missing x2 wheel nuts (5.2.1 (a) (i))

MAJOR Rear Registration plate incorrect incorrect spacing (0.1 (c))

Advice Corrosion under-vehicle in places

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Rear Road wheel fixing missing wheel nut (5.2.1 (a) (i))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))



MOT #12	2019-04-03 12:38
MOT test number	171829476410
Result	✓ Passed
Advice	Rear All direction indicators slightly discoloured x 2 (4.4.3 (a))
MOT #11	2018-03-19 14:11
MOT test number	383883772007
Result	✓ Passed
MOT #10	2017-03-14 16:44
MOT test number	204546386996
Result	✓ Passed
MOT #9	2016-03-03 10:04
MOT test number	616145980404
Result	✓ Passed
MOT #8	2015-03-07 10:14
MOT test number	138686165404
Result	✓ Passed
MOT #7	2014-03-15 09:30
MOT test number	479544774016
Result	✓ Passed
MOT #6	2013-03-16 09:34
MOT test number	235505273006
Result	✓ Passed

**MOT #5** 2012-02-27 17:01**MOT test number** 998108752054**Result** ✓ Passed**MOT #4** 2011-05-19 09:53**MOT test number** 169449531192**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #3** 2011-03-16 09:32**MOT test number** 718095971049**Result** ✓ Passed**Advice** Offside Front Seat belt attachment fitting slightly deteriorated (5.2.3)**MOT #2** 2010-02-24 09:23**MOT test number** 431155250059**Result** ✓ Passed**Advice** Offside Rear brake disc slightly scored (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**MOT #1** 2009-03-12 13:47**MOT test number** 460541279011**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
26 July 2022

✕
MOT

Expired:
2 October 2021

Tax status	Expired at 26 July 2022
Days left	643 days too late
MOT expiry date	2 October 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-03-20
Last registration	2020-10-03
Complete history	See info



Registration #1	2006-03-20	8 mi
Registration #2	2009-03-12	34.708 mi
Registration #3	2010-02-24	45.245 mi
Registration #4	2011-03-16	55.294 mi
Registration #5	2011-05-19	55.827 mi
Registration #6	2012-02-27	55.970 mi
Registration #7	2013-03-16	62.833 mi
Registration #8	2014-03-15	69.494 mi
Registration #9	2015-03-07	77.325 mi
Registration #10	2016-03-07	85.156 mi
Registration #11	2017-03-07	92.987 mi
Registration #12	2018-03-07	100.818 mi
Registration #13	2019-03-07	108.649 mi
Registration #14	2020-03-07	116.480 mi
Registration #15	2021-03-07	124.311 mi
Registration #16	2022-03-07	132.142 mi
Registration #17	2023-03-07	140.000 mi
Registration #18	2024-03-07	147.858 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	060407132209BG