



HWI4GYZ

report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg





Internet history

Entry 1

Date	2021-09-09
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #8</b>	2023-03-22 17:23
<b>MOT test number</b>	797264926008
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-03-23

<b>MOT #7</b>	2023-03-22 12:08
<b>MOT test number</b>	920837764381
<b>Result</b>	✗ Failed
<b>Minor</b>	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>MAJOR</b>	Offside Front Road wheel fixing missing (5.2.1 (a) (i))
<b>Minor</b>	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>MAJOR</b>	Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

<b>MOT #6</b>	2022-03-24 13:27
<b>MOT test number</b>	459400047786
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Rear Exhaust Heat Shield Loose

<b>MOT #5</b>	2021-02-26 17:24
<b>MOT test number</b>	968360941189
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge 3.5mm (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Central Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge 3.3mm (5.2.3 (e))
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2020-02-07 12:38**MOT test number** 411360282429**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 225/50/17 98w (5.2.3 (e))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #3** 2019-02-02 10:15**MOT test number** 827670349613**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #2** 2018-02-10 11:51**MOT test number** 249059310735**Result** ✓ Passed**MOT #1** 2017-02-24 10:16**MOT test number** 275053866769**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>HW14GYZ</b>
Plate since	2019-03-29
Current registration	<b>HW14GYZ</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-05-08
Last registration	2023-03-22
Complete history	<a href="#">See info</a>



Registration #1	2014-05-08	13 mi
Registration #2	2017-02-24	21.681 mi
Registration #3	2018-02-10	31.258 mi
Registration #4	2019-02-02	47.209 mi
Registration #5	2020-02-07	62.341 mi
Registration #6	2020-05-20	75.277 mi
Registration #7	2020-05-20	75.277 mi
Registration #8	2020-05-20	75.277 mi
Registration #9	2020-05-20	75.277 mi
Registration #10	2020-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1688 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	ET47075