



report date: 2024-03-28

## General information

Make	VOLVO
Model	S40 D S
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-06-09
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #17	2024-02-13 16:37
MOT test number	544810381220
Result	✓ Passed
Next expiry date	2025-02-12

MOT #16	2024-01-29 17:03
MOT test number	146861006343
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2023-02-06 11:34
MOT test number	106076343259
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2022-01-26 11:22

**MOT test number**

873049115288

**Result**

✓ Passed

- Advice** Rear General corrosion to nearside and offside suspension components
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear most bush (5.3.4 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Stone chip to wind screen
- Advice** Items removed from driver's view prior to test From mirror
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front and rear number plates cleaned before test in order to fully inspect

**MOT #13**

2021-02-05 13:09

**MOT test number**

255708864317

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing + Stones Embedded (5.2.3 (d) (ii))

**MOT #12**

2019-12-10 11:19

**MOT test number**

824430490772

**Result**

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2019-12-09 11:36**MOT test number** 104024457542**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2018-12-07 11:28**MOT test number** 763745682121**Result** ✓ Passed**MOT #9** 2017-12-08 13:55**MOT test number** 143508174409**Result** ✓ Passed**Advice** Offside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2016-12-14 11:14**MOT test number** 186838979557**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2015-12-04 14:35**MOT test number** 186634136215**Result** ✓ Passed

**MOT #6** 2014-12-12 11:28**MOT test number** 318426044396**Result** ✓ Passed**MOT #5** 2013-12-09 12:11**MOT test number** 716613743314**Result** ✓ Passed**MOT #4** 2012-12-17 16:31**MOT test number** 695072052389**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-12-17 16:31**MOT test number** 449142352309**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2011-12-08 11:07**MOT test number** 259052141393**Result** ✓ Passed**MOT #1** 2010-12-10 14:32**MOT test number** 760804140349**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
12 February 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	12 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-31
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2007-12-31	26 mi
Registration #2	2010-12-10	20.638 mi
Registration #3	2011-12-08	29.090 mi
Registration #4	2012-12-17	37.883 mi
Registration #5	2013-12-09	44.733 mi
Registration #6	2014-12-12	50.563 mi
Registration #7	2015-12-04	55.017 mi
Registration #8	2016-12-14	60.321 mi
Registration #9	2017-12-08	64.648 mi
Registration #10	2018-12-01	68.975 mi
Registration #11	2019-12-01	73.302 mi
Registration #12	2020-12-01	77.629 mi
Registration #13	2021-12-01	81.956 mi
Registration #14	2022-12-01	86.283 mi
Registration #15	2023-12-01	90.610 mi
Registration #16	2024-02-13	94.937 mi
Registration #17	2024-02-13	94.937 mi
Registration #18	2024-02-13	94.937 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	130531