



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO 16V DYNAMIC SPORT
Colour	Red
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	125 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.1 mpg





## Internet history

### Entry 1

Date	2021-06-07
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT #19</b>	2022-01-14 09:47
<b>MOT test number</b>	273691060699
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-01-13
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge AND PERISHED (5.2.3 (e))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge AND PERISHED (5.2.3 (e))

<b>MOT #18</b>	2021-01-22 16:57
<b>MOT test number</b>	859046192901
<b>Result</b>	✓ Passed
<b>Minor</b>	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
<b>Advice</b>	Nearside Play in steering rack inner joint(s)
<b>Minor</b>	Offside Obligatory mirror slightly loose (3.3 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge 205/45/17 (5.2.3 (e))

<b>MOT #17</b>	2021-01-22 15:55
<b>MOT test number</b>	926176005529
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Play in steering rack inner joint(s)
<b>Minor</b>	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
<b>Pass with rectification</b>	Nearside Headlamp aim too far to the right (4.1.2 (a))
<b>Fail</b>	Exhaust emissions likely to be affected by an exhaust leak front pipe (8.2.1.1 (b))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge 205/45/17 (5.2.3 (e))
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>Minor</b>	Offside Obligatory mirror slightly loose (3.3 (b) (i))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))



MOT #16 2020-02-08 11:31

MOT test number 977035863310

Result ✔ Passed

MOT #15 2019-02-16 09:30

MOT test number 624197404106

Result ✔ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-02-12 12:02

MOT test number 783075249959

Result ✘ Failed

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Power steering malfunctioning (2.1.5 (a))

MOT #13 2017-03-15 10:28

MOT test number 581151517206

Result ✔ Passed

**Advice** Oil leak

**Advice** Rear coil spring corroded Both (2.4.C.1b)

MOT #12 2017-03-13 13:43

MOT test number 759874429250

Result ✘ Failed

**Advice** Oil leak

**Fail** Offside Rear Rear wheel bearing has excessive play (2.6.2)

**Advice** Rear coil spring corroded Both (2.4.C.1b)



MOT #11 2016-03-11 09:27

MOT test number 418912166662

Result ✔ Passed

MOT #10 2016-03-08 18:42

MOT test number 307255561806

Result ✘ Failed

**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)

**Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #9 2015-09-08 11:04

MOT test number 827223305963

Result ✔ Passed

**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

MOT #8 2015-09-08 11:04

MOT test number 488133241686

Result ✘ Failed

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

MOT #7 2014-09-06 11:35

MOT test number 786239244250

Result ✔ Passed

**Notice** Rear box corroded

**Notice** Radiator leaking



**MOT #6** 2014-09-06 10:29

**MOT test number** 838669344216

**Result** ✗ Failed

- Notice** Rear box corroded
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Notice** Radiator leaking

**MOT #5** 2013-09-18 12:20

**MOT test number** 525091163277

**Result** ✓ Passed

- Notice** Front tyres on legal limit
- Notice** Rear exhaust box corroded

**MOT #4** 2012-09-14 10:03

**MOT test number** 755028752274

**Result** ✓ Passed

- Notice** Low on coolant
- Notice** Front tyres wearing on inner edges
- Notice** Front pads low
- Notice** Rear box corroded

**MOT #3** 2011-09-13 15:07

**MOT test number** 515876951225

**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)



<b>MOT #2</b>	2010-08-31 15:18
<b>MOT test number</b>	932093440253
<b>Result</b>	✓ Passed
<b>Notice</b>	Nearside drive shaft oil leak
<b>Notice</b>	Front pads low and discs worn

<b>MOT #1</b>	2010-08-31 13:04
<b>MOT test number</b>	681613540277
<b>Result</b>	✗ Failed
<b>Notice</b>	Nearside drive shaft oil leak
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Notice</b>	Front pads low and discs worn
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)




**Damage history**

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra FIAT salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	21
<b>First mileage registration</b>	2007-09-18
<b>Last registration</b>	2022-01-14
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2007-09-18	19 mi
<b>Registration #2</b>	2010-08-31	38.320 mi
<b>Registration #3</b>	2010-08-31	38.320 mi
<b>Registration #4</b>	2011-09-13	41.534 mi
<b>Registration #5</b>	2012-09-14	44.940 mi
<b>Registration #6</b>	2013-09-18	47.729 mi
<b>Registration #7</b>	2014-09-06	52.657 mi
<b>Registration #8</b>	2014-09-06	52.657 mi
<b>Registration #9</b>	2015-09-08	63.357 mi
<b>Registration #10</b>	2015-09-08	63.357 mi
<b>Registration #11</b>	2016-03-08	68.029 mi
<b>Registration #12</b>	2016-03-08	68.029 mi
<b>Registration #13</b>	2016-03-08	68.029 mi
<b>Registration #14</b>	2016-03-08	68.029 mi
<b>Registration #15</b>	2016-03-08	68.029 mi
<b>Registration #16</b>	2016-03-08	68.029 mi
<b>Registration #17</b>	2016-03-08	68.029 mi
<b>Registration #18</b>	2016-03-08	68.029 mi
<b>Registration #19</b>	2016-03-08	68.029 mi
<b>Registration #20</b>	2016-03-08	68.029 mi
<b>Registration #21</b>	2016-03-08	68.029 mi

[More info >](#)



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1060 kg
Max. allowed weight	2635 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1134831