



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | MINI |
| Model | MINI (R60) |
| Colour | White |
| Year of manufacture | 2011 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 150 BHP |
| Max. torque | 330 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 130 g/km |
| CO2 label | D |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-07 |
| Pictures | 12 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-23 |
| MOT pass rate | 91 % |
| MOT passed | 10 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #11 | 2023-08-16 11:07 |
| MOT test number | 833037636377 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-23 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|---|
| MOT #10 | 2022-08-24 10:52 |
| MOT test number | 316151762679 |
| Result | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Parking brake lever has little reserve travel |

| | |
|-----------------|------------------|
| MOT #9 | 2021-08-09 08:38 |
| MOT test number | 914119223514 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #8 | 2020-08-13 11:01 |
| MOT test number | 243415996144 |
| Result | ✓ Passed |

**MOT #7** 2019-08-13 10:45**MOT test number** 368403182665**Result** ✓ Passed**Advice** Nearside Front Inner Road wheel slightly distorted rim (5.2.2 (c) (i))**Advice** Undertray not fully secure (8.1.1 (b) (i))**MOT #6** 2018-08-15 12:33**MOT test number** 382881110251**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** CUTS TO N/S/F TYRE TREAD**MOT #5** 2017-08-17 14:21**MOT test number** 267477245288**Result** ✓ Passed**MOT #4** 2016-08-23 18:06**MOT test number** 369091067173**Result** ✓ Passed**MOT #3** 2016-08-23 18:06**MOT test number** 443982056515**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)



| | |
|-----------------|--|
| MOT #2 | 2015-06-26 12:02 |
| MOT test number | 789627075142 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #1 | 2014-05-12 10:22 |
| MOT test number | 399252734123 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
23 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 217 |
| MOT expiry date | 23 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-29 |
| Current registration | |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2011-05-19 |
| Last registration | 2023-08-16 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-05-19 | 15 mi |
| Registration #2 | 2014-05-12 | 31.346 mi |
| Registration #3 | 2015-06-26 | 35.532 mi |
| Registration #4 | 2016-08-23 | 41.005 mi |
| Registration #5 | 2016-08-23 | 41.005 mi |
| Registration #6 | 2017-08-17 | 50.236 mi |
| Registration #7 | 2018-08-15 | 54.361 mi |
| Registration #8 | 2019-08-20 | 55.277 mi |
| Registration #9 | 2019-08-20 | 55.277 mi |
| Registration #10 | 2019-08-20 | 55.277 mi |
| Registration #11 | 2019-08-20 | 55.277 mi |
| Registration #12 | 2019-08-20 | 55.277 mi |
| Registration #13 | 2019-08-20 | 55.277 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2005 mm |
| Height | 1557 mm |
| Length | 4299 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1365 kg |
| Max. allowed weight | 1855 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 51 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 4 |

Engine number

71407850