



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TRENDLINE TDI (100BHP)
Colour	Grey
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg



**MOT history**

MOT #23	2023-07-13 15:31
MOT test number	113549039551
Result	✓ Passed
Next expiry date	2024-07-12

MOT #22	2022-03-03 11:31
MOT test number	973737681346
Result	✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Axle swivel pins and bushes swivel pin and/or bush slightly worn both rears (5.1.2 (b) (i))

MOT #21	2021-03-04 10:06
MOT test number	880257669520
Result	✓ Passed

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Rear exhaust back box outer skin corroded

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Axle swivel pins and bushes swivel pin and/or bush slightly worn both rear (5.1.2 (b) (i))

**MOT #20**

2020-02-27 16:26

MOT test number

175637492552

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge On 2mm . (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Service brake fluctuating, but not excessively Both. (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 2.5mm and wearing on inner edge. (5.2.3 (e))
- Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement Both strut top bushes slight lift. (5.3.4 (a) (i))

MOT #19

2020-02-27 11:15

MOT test number

168429962485

Result

✗ Failed

- Advice** Front Service brake fluctuating, but not excessively Both. (1.2.1 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge On 2mm . (5.2.3 (e))
- Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement Both strut top bushes slight lift. (5.3.4 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge On 2.5mm and wearing on inner edge. (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #18**

2019-02-25 17:26

MOT test number

688355384765

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both rear tyres wearing on inner edge. (5.2.3 (e))
- Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement Both front strut top bushes have slight lift. (5.3.4 (a) (i))

MOT #17

2019-02-25 11:21

MOT test number

979463589512

Result

✗ Failed

- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both rear tyres wearing on inner edge. (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Undertray not fully secure (8.1.1 (b) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Exhaust mounting defective Center exhaust hanger snapped and center clamp corroding. (6.1.2 (a))
- Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement Both front strut top bushes have slight lift. (5.3.4 (a) (i))

**MOT #16**

2018-02-27 17:04

MOT test number

957403830322

Result

✓ Passed

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Center exhaust hanger snapped but exhaust still secure.

Advice

Front Macpherson strut has slight movement at the upper attachment Both front strut tops.
(2.5.A.1c)

MOT #15

2018-02-27 11:49

MOT test number

998635579618

Result

✗ Failed

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Fail

Offside Front Direction indicator incorrect colour (1.4.A.2f)

Fail

Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Center exhaust hanger snapped but exhaust still secure.

Advice

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Front Macpherson strut has slight movement at the upper attachment Both front strut tops.
(2.5.A.1c)

MOT #14

2017-03-01 17:52

MOT test number

649236267186

Result

✓ Passed

Advice

Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

Advice

Offside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice

Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #13**

2016-02-23 17:38

MOT test number

488641636381

Result

✓ Passed

- Advice** Rear Both rear tyre wearing uneven on inner edges.
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Revers light not working.
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #12

2016-02-23 11:41

MOT test number

708844828757

Result

✗ Failed

- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Revers light not working.
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Rear Both rear tyre wearing uneven on inner edges.
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2014-10-16 09:25**MOT test number** 815279484211**Result** ✓ Passed**MOT #10** 2013-09-23 13:19**MOT test number** 877856063277**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #9** 2012-08-24 07:42**MOT test number** 466987732213**Result** ✓ Passed**MOT #8** 2012-08-20 14:08**MOT test number** 756813632225**Result** ✗ Failed**Fail** Brake pedal creeps down under servo assistance and touches the floor (3.3.C.3)**MOT #7** 2012-03-23 15:55**MOT test number** 809163182064**Result** ✓ Passed**MOT #6** 2011-03-01 16:59**MOT test number** 935500961075**Result** ✓ Passed

**MOT #5** 2011-03-01 12:10**MOT test number** 789650261086**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Front brake discs are badly corroded on insides**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #4** 2010-03-25 11:35**MOT test number** 313974180051**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Inner Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Inner Front brake disc slightly scored (3.5.1h)**MOT #3** 2009-03-26 10:21**MOT test number** 411015489098**Result** ✓ Passed**MOT #2** 2008-03-25 16:22**MOT test number** 122175688400**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2008-03-25 16:16
MOT test number	881905288021
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Nail in nearside rear tyre



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-04-15
Last registration	2023-07-13
Complete history	See info



Registration #1	2005-04-15	21 mi
Registration #2	2008-03-25	27.114 mi
Registration #3	2008-03-25	27.114 mi
Registration #4	2009-03-26	31.563 mi
Registration #5	2010-03-25	36.036 mi
Registration #6	2011-03-01	40.610 mi
Registration #7	2011-03-01	40.611 mi
Registration #8	2012-03-23	43.935 mi
Registration #9	2012-08-20	44.860 mi
Registration #10	2012-08-24	44.860 mi
Registration #11	2013-09-23	60.069 mi
Registration #12	2014-10-16	79.613 mi
Registration #13	2015-05-20	95.277 mi
Registration #14	2015-05-20	95.277 mi
Registration #15	2015-05-20	95.277 mi
Registration #16	2015-05-20	95.277 mi
Registration #17	2015-05-20	95.277 mi
Registration #18	2015-05-20	95.277 mi
Registration #19	2015-05-20	95.277 mi
Registration #20	2015-05-20	95.277 mi
Registration #21	2015-05-20	95.277 mi
Registration #22	2015-05-20	95.277 mi
Registration #23	2015-05-20	95.277 mi
Registration #24	2015-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1462 mm
Length	4703 mm
Wheel base	2703 mm
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

AVB 382931