



REIOPNV

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 SWB VAN 104TDI
Colour	White
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-07-31
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	31
Total items failed	3

MOT #17	2023-08-01 15:45
MOT test number	114669864490
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Front windscreen wiper just clear screen
Advice	N/s and o/s rear shocks corroded and bushes worn
Advice	Centre exhaust clamp corroded
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	N/s and o/s front lower arm rear bushes perished

MOT #16	2023-08-01 13:27
MOT test number	500992285253
Result	✗ Failed
Advice	N/s and o/s rear shocks corroded and bushes worn
Advice	Centre exhaust clamp corroded
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	N/s and o/s front lower arm rear bushes perished
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Front windscreen wiper just clear screen

**MOT #15**

2022-04-04 15:09

**MOT test number**

224340253197

**Result**

✓ Passed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #14**

2022-04-04 14:21

**MOT test number**

471390574811

**Result**

✗ Failed

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MAJOR** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**DANGEROUS** Nearside Front Tyre has ply or cords exposed inner sidewall (5.2.3 (d) (ii))

**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))

**MAJOR** Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #13**

2021-04-07 13:07

**MOT test number**

507795170173

**Result**

✓ Passed

**MOT #12**

2021-03-25 16:49

**MOT test number**

707706209765

**Result**

✗ Failed

**MAJOR** Offside Rear Position lamp showing white light to the rear Hole in lens (4.2.3 (a) (ii))

**MAJOR** Nearside Rear Anti-roll bar pin or bush excessively worn D- bushes deteriorated worn (5.3.4 (a) (i))

**MAJOR** Nearside Reversing lamp inoperative (4.6.1 (a))

**MAJOR** Rear Exhaust system insecure Silencer clamp corroded cracked (6.1.2 (a))

**MOT #11** 2020-09-11 14:29**MOT test number** 974021722174**Result** ✓ Passed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #10** 2020-09-11 08:21**MOT test number** 762607239389**Result** ✗ Failed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2019-09-10 11:26**MOT test number** 754054302402**Result** ✓ Passed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #8** 2018-09-10 08:25**MOT test number** 913423478641**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2017-09-11 11:14**MOT test number** 768419071580**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

**MOT #6** 2016-09-13 09:13**MOT test number** 290635767830**Result** ✓ Passed**Advice** Offside Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)**MOT #5** 2015-07-28 12:12**MOT test number** 456379805276**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2014-07-31 09:37**MOT test number** 778482514237**Result** ✓ Passed**MOT #3** 2014-07-31 09:37**MOT test number** 706862214277**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #2** 2013-07-02 13:10**MOT test number** 158363183145**Result** ✓ Passed**MOT #1** 2013-07-02 13:10**MOT test number** 585453783103**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
31 July 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		31 July 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>RE10PNV</b>
Plate since	2019-03-29
Current registration	 <b>RE10PNV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-25
Last registration	2023-08-01
Complete history	<a href="#">See info</a>



Registration #1	2010-05-25	9 mi
Registration #2	2013-07-02	38.401 mi
Registration #3	2014-07-31	48.170 mi
Registration #4	2015-07-28	57.486 mi
Registration #5	2016-09-13	73.734 mi
Registration #6	2017-09-11	89.773 mi
Registration #7	2018-09-10	105.517 mi
Registration #8	2019-09-10	123.093 mi
Registration #9	2020-09-10	141.669 mi
Registration #10	2021-09-10	160.245 mi
Registration #11	2022-09-10	178.821 mi
Registration #12	2023-09-10	197.397 mi
Registration #13	2024-09-10	215.973 mi
Registration #14	2025-09-10	234.549 mi
Registration #15	2026-09-10	253.125 mi
Registration #16	2027-09-10	271.701 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Length	4405 mm

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	BLS C56612