



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	10.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.797 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	70.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	92 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-03
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-21
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	41
Total items failed	6

MOT #21	2024-04-22 08:34
MOT test number	589341999898
Result	✓ Passed
Next expiry date	2025-04-21
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #20	2024-04-17 08:04
MOT test number	734529480008
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #19	2023-04-14 08:28
MOT test number	258148760542
Result	✓ Passed
Advice	Rear parking brake 16% efficiency
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #18** 2022-04-11 13:53**MOT test number** 764521070529**Result** ✓ Passed**MOT #17** 2022-04-11 13:53**MOT test number** 460869866841**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #16** 2021-04-19 13:00**MOT test number** 423692482035**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #15** 2020-02-25 14:34**MOT test number** 710825605453**Result** ✓ Passed**MOT #14** 2019-09-09 11:51**MOT test number** 537546040602**Result** ✓ Passed**Advice** Nearside front tyre tread slightly low and close to legal limit

**MOT #13**

2019-03-07 10:51

MOT test number

466729774651

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Rear Coil spring corroded both (5.3.1 (b) (i))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12

2018-09-11 12:35

MOT test number

940245102397

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Rear Coil spring corroded both (5.3.1 (b) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11

2018-03-05 14:36

MOT test number

440180442515

Result

✓ Passed

Advice

Rear coil spring corroded both (2.4.C.1b)

MOT #10

2017-09-04 10:14

MOT test number

208324143025

Result

✓ Passed

Advice

Rear coil spring corroded both (2.4.C.1b)

**MOT #9** 2017-03-09 10:45**MOT test number** 695583960991**Result** ✓ Passed**Advice** Rear coil spring corroded both (2.4.C.1b)**MOT #8** 2017-02-02 12:20**MOT test number** 634943511585**Result** ✓ Passed**MOT #7** 2016-05-04 14:46**MOT test number** 101083491814**Result** ✓ Passed**Advice** Rear coil spring corroded n/s and o/s (2.4.C.1b)**Advice** Rear exhaust heat shield condition**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear tyre cracks in side wall**Advice** Front coil spring corroded n/s and o/s (2.4.C.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front tyre cracks in side wall**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6**

2016-05-04 09:29

MOT test number

190041316373

Result**✗ Failed**

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer side wall (4.1.D.1a)

Advice Rear coil spring corroded n/s and o/s (2.4.C.1b)

Advice Rear exhaust heat shield condition

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Rear tyre cracks in side wall

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Front coil spring corroded n/s and o/s (2.4.C.1b)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Offside Front tyre cracks in side wall

MOT #5

2015-05-14 14:41

MOT test number

266424335467

Result**✓ Passed**

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice Under-trays fitted obscuring some underside components

Notice Rear o/s tyre cracks in side walls

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #4

2014-05-28 13:28

MOT test number

285798244492

Result**✓ Passed**



MOT #3	2014-02-24 15:00
MOT test number	117315854098
Result	✓ Passed

MOT #2	2014-02-24 15:00
MOT test number	597445254052
Result	✗ Failed
<div>Pass with rectification</div> Centre Stop lamp not working (1.2.1b)	

MOT #1	2013-02-14 11:50
MOT test number	767685943090
Result	✓ Passed
<div>Notice</div> Rear brakes binding slightly	



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 April 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	SG10URK
Plate since	2019-03-29
Current registration	SG10URK
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-03-01
Last registration	2024-04-22
Complete history	See info



Registration #1	2010-03-01	16 mi
Registration #2	2013-02-14	24.978 mi
Registration #3	2014-02-24	34.162 mi
Registration #4	2014-05-28	34.879 mi
Registration #5	2015-05-14	39.411 mi
Registration #6	2016-05-04	43.517 mi
Registration #7	2016-05-04	43.518 mi
Registration #8	2017-02-02	47.831 mi
Registration #9	2017-03-09	48.074 mi
Registration #10	2017-09-04	60.127 mi
Registration #11	2018-03-05	71.827 mi
Registration #12	2018-03-05	71.827 mi
Registration #13	2018-03-05	71.827 mi
Registration #14	2018-03-05	71.827 mi
Registration #15	2018-03-05	71.827 mi
Registration #16	2018-03-05	71.827 mi
Registration #17	2018-03-05	71.827 mi
Registration #18	2018-03-05	71.827 mi
Registration #19	2018-03-05	71.827 mi
Registration #20	2018-03-05	71.827 mi
Registration #21	2018-03-05	71.827 mi
Registration #22	2018-03-05	71.827 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	82%
Pedestrian	68%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1745 mm
Height	1490 mm
Length	4460 mm
Wheel base	2700 mm
Kerb weight	1420 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	1ZX4490943
---------------	------------