





report date: 2024-03-29

General information

Make	BMW
Model	430 430D XDRIVE M SPORT GRAN COUPE
Colour	Black
Year of manufacture	2015
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	56.5 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 2

Date 2021-11-23

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2021-10-13	
Pictures	72	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-01-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #9	2024-01-02 11:21
MOT test number	654452139982
Result	✓ Passed
Next expiry date	2025-01-01

MOT #8		2022-12-08 08:26
MOT test	number	952573583966
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7	2022-11-30 16:49
MOT test number	471629247198
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i Fail Offside Rear Inner Road wheel fractured (5.2.2 (a))	ii))

MOT #6	2021-12-15 11:03
MOT test number	466797819777
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

SL15GBF

report date: 2024-03-29

✓ Passed

 MOT #5
 2021-07-07 14:50

 MOT test number
 720652599397

Advice Tyre pressure warning light on

MOT #4 2020-07-18 09:49

MOT test number 990790034155

Result \rightarrow Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner brake surface (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

MOT #3 2019-04-18 15:26

MOT test number 447017587476

Result ✓ Passed

MOT #2 2019-02-28 16:32

MOT test number 412563687239

Result × Failed

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure poor puncture repair carried out to outer shoulder of run flat tyre causing lump (5.2.3 (d) (ii))

MOT #1 2018-03-07 17:53

MOT test number 339898907567

Result Passed

Advice Engine cover and under tray fitted obstruct view

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	1 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-04-30
Last registration	2024-01-02
Complete history	See info



2015-04-30	22 mi
2018-03-07	11.292 mi
2019-02-28	19.977 mi
2019-04-18	20.272 mi
2020-07-18	39.501 mi
2021-07-07	41.299 mi
	11.777 es
	2018-03-07 2019-02-28 2019-04-18 2020-07-18

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video

View the complete BMW factory list for this vehicle <u>here</u>.



More info >

Dimensions & weight

Width	1825 mm
Height	1412 mm
Length	4638 mm
Wheel base	2810 mm
Kerb weight	1675 kg
Max. allowed weight	2235 kg

Additional information

Fuel tank capacity	57 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 60589201