





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	E E 220 D SE
Colour	Grey
Year of manufacture	2017
Top speed	149 mph
0 - 100 km/h	7.3 seconds
0 - 60 mph	7.3 seconds
Gearbox	9 speed automatic

Engine & fuel consumption

Power	143 kW / 195 HP / 191 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.950 сс
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date	2022-07-20

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

✓ Passed

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

Result

MOT expiry date	2024-08-08
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #6	2023-08-05 08:30
MOT test number	542276488787
Result	✓ Passed
Next expiry date	2024-08-08

MOT #5	2023-08-05 08:30
MOT test number	720073023866
Result	X Failed
Pass with rectification nail in tread (5.2.3 (e))	Offside Rear Tyre tread depth below requirements of 1.6mm 1mm central tread,
Pass with rectification tread (5.2.3 (e))	Nearside Rear Tyre tread depth below requirements of 1.6mm 1mm central

MOT #4	2022-08-09 15:48
MOT test number	956870480861
Result	✓ Passed
MOT #3	2021-07-08 07:56
MOT test number	168767454299
Result	✓ Passed
MOT #2	2020-07-30 08:27
MOT test number	366436873620

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2020-07-29 08:55

MOT test number 642177993299

Result X Failed

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES-BENZ salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK SIV
Plate since	
Current registration	NK SIE
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-08-10
Last registration	2023-08-05
Complete history	See info



Registration #1	2017-08-10	19 mi
Registration #2	2020-07-29	38.678 mi
Registration #3	2020-07-30	38.678 mi
Registration #4		11.777 es
Registration #5	2021-07-08	44.019 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	
View the complete MEDCEDES BEN7 factory list for this	
View the complete MERCEDES-BENZ factory list for this vehicle here.	More info >

Safety ratings

NCAP rating	****
Adult	86%
Children	77%
Pedestrian	59%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1468 mm
Length	4923 mm
Wheel base	2939 mm
Kerb weight	1600 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack ca uk	nago 11/1

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	65492080146887