



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	URBAN CRUISER D-4D
Colour	Blue
Year of manufacture	2011
Top speed	109 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 2

Date	2022-11-23
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-02-05
Pictures	9
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-20
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	25
Total items failed	14

MOT #16	2024-03-21 09:49
MOT test number	696499314726
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Nearside Rear fluid leak at rear
Advice	Coil spring corroded both rear coil springs (5.3.1 (b) (i))

MOT #15	2024-03-20 14:56
MOT test number	528815662740
Result	✗ Failed
Fail	Front Lower Suspension component ball joint likely to become detached split pin missing (5.3.4 (a) (ii))
Advice	Coil spring corroded both rear coil springs (5.3.1 (b) (i))
Advice	Nearside Rear fluid leak at rear
Fail	Nearside Rear Brake pipe excessively corroded at flexi (1.1.11 (c))
Minor	Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Both rear cables insecure at rear

MOT #14	2023-03-14 15:34
MOT test number	192005100785
Result	✓ Passed

**MOT #13** 2023-03-13 15:20**MOT test number** 601124086318**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12** 2022-05-11 15:17**MOT test number** 930836502538**Result** ✓ Passed**MOT #11** 2020-12-11 09:58**MOT test number** 140429874997**Result** ✓ Passed**MOT #10** 2020-12-08 16:11**MOT test number** 787398515249**Result** ✗ Failed**Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearmost (5.3.4 (a) (i))

**MOT #9**

2020-01-13 12:32

MOT test number

886035642592

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both discs worn and corroded (1.1.14 (a) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge both tyres wearing on edges (5.2.3 (e))

MOT #8

2020-01-09 13:55

MOT test number

796190394206

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both discs worn and corroded (1.1.14 (a) (ii))

Advice Rear Tyre worn close to legal limit/worn on edge both tyres wearing on edges (5.2.3 (e))

Fail Nearside Headlamp levelling device inoperative (4.1.5 (a))

MOT #7

2019-01-07 11:35

MOT test number

904985998412

Result

✓ Passed

Advice Fuel Pipe/s corroded filler pipes

Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #6

2018-01-12 09:42

MOT test number

817610301670

Result

✓ Passed

**MOT #5** 2017-01-06 14:03**MOT test number** 698101133121**Result** ✓ Passed**Advice** Fuel filler pipes has plastic cover insecure**MOT #4** 2016-01-12 10:57**MOT test number** 682359551626**Result** ✓ Passed**MOT #3** 2016-01-12 08:43**MOT test number** 817303687609**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2015-01-13 14:13**MOT test number** 577943015096**Result** ✓ Passed**Notice** O/s/f/ tyre worn on inner edge**MOT #1** 2015-01-13 14:13**MOT test number** 479863515053**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** O/s/f/ tyre worn on inner edge**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 March 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-12
Last registration	2024-03-21
Complete history	See info



Registration #1	2011-12-12	8 mi
Registration #2	2015-01-13	25.119 mi
Registration #3	2016-01-12	43.016 mi
Registration #4	2016-01-12	43.020 mi
Registration #5	2017-01-06	67.220 mi
Registration #6	2018-01-12	84.626 mi
Registration #7	2019-01-07	95.843 mi
Registration #8	2020-01-09	106.164 mi
Registration #9	2020-01-13	106.164 mi
Registration #10	2020-01-13	106.164 mi
Registration #11	2020-01-13	106.164 mi
Registration #12	2020-01-13	106.164 mi
Registration #13	2020-01-13	106.164 mi
Registration #14	2020-01-13	106.164 mi
Registration #15	2020-01-13	106.164 mi
Registration #16	2020-01-13	106.164 mi
Registration #17	2020-01-13	106.164 mi
Registration #18	2020-01-13	106.164 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1540 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1265 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1ND1195881