



General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE
Colour	Blue
Year of manufacture	2011
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-08-07
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	13

MOT #14 2023-10-03 08:55

MOT test number 533146749666

Result ✓ Passed

Next expiry date 2024-10-12

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Central Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #13 2022-10-13 16:21

MOT test number 534444296757

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-10-10 08:46

**MOT test number**

948928961666

**Result****✗ Failed**

- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Nearside Windscreen wiper not working (3.4 (a))
- Advice** Nearside Rear Passenger seat(s) missing at time of test
- Fail** Nearside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #11**

2021-10-01 14:08

**MOT test number**

722952763548

**Result****✓ Passed**

- Advice** Nearside Play in steering rack inner joint(s)

**MOT #10**

2021-10-01 09:04

**MOT test number**

365129818227

**Result****✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #9** 2020-10-02 09:19**MOT test number** 108755983118**Result** ✓ Passed**MOT #8** 2019-09-20 15:38**MOT test number** 531082641657**Result** ✓ Passed**MOT #7** 2019-09-20 10:14**MOT test number** 896499022416**Result** ✗ Failed**Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**MOT #6** 2018-09-15 10:11**MOT test number** 726570807716**Result** ✓ Passed**MOT #5** 2018-09-15 10:11**MOT test number** 500649164331**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #4** 2017-10-05 08:10**MOT test number** 266539555055**Result** ✓ Passed



MOT #3	2016-09-17 10:00
MOT test number	201771070218
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Seat belt flexible stalk damaged but not likely to lead to failure under load (5.2.4a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Both front wipers smearing

MOT #2	2015-10-10 08:23
MOT test number	922347332104
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Rear Shock absorber has a slightly worn bush (2.7.4)

MOT #1	2014-10-11 09:33
MOT test number	775084084289
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-12
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2011-10-12	20 mi
Registration #2	2014-10-11	19.874 mi
Registration #3	2015-10-10	25.055 mi
Registration #4	2016-09-17	30.190 mi
Registration #5	2017-10-05	35.468 mi
Registration #6	2018-09-15	40.371 mi
Registration #7	2018-09-15	40.371 mi
Registration #8	2019-09-20	49.525 mi
Registration #9	2019-09-20	49.525 mi
Registration #10	2019-09-20	49.525 mi
Registration #11	2019-09-20	49.525 mi
Registration #12	2019-09-20	49.525 mi
Registration #13	2019-09-20	49.525 mi
Registration #14	2019-09-20	49.525 mi
Registration #15	2019-09-20	49.525 mi
Registration #16	2019-09-20	49.525 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4246348