





report date: 2024-03-28

General information

| Make | RENAULT |
|---------------------|----------------------------------|
| Model | MASTER LM35 BUSINESS DCI S/R P/V |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 89 mph |
| 0 - 60 mph | 15.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 125 BHP |
|-------------------------|---------------------|
| Max. torque | 310 Nm at 1.500 rpm |
| Engine capacity | 2.298 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 30.7 mpg |
| Consumption extra urban | 40.4 mpg |
| Consumption combined | 36.2 mpg |
| CO2 emission | 211 g/km |
| CO2 label | K |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

| E | n | t | r٧ | , | 3 |
|---|---|---|----|---|---|
| | | | | | |

| Date | 2021-11-16 |
|---------------|--------------------|
| Pictures | 0 |
| Listing price | <u>View report</u> |

source: cargurus.co.uk

Entry 2

| Date | 2021-09-16 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

Entry 1

| Date | 2021-09-16 | |
|---------------|-------------|--|
| Pictures | 0 | |
| Listing price | View report | |

source: heycar.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-10-10 |
|--------------------|------------|
| MOT pass rate | 56 % |
| MOT passed | 5 |
| Failed MOT tests | 4 |
| Total advice items | 8 |
| Total items failed | 7 |

| MOT #9 | 2023-10-11 15:37 |
|--|------------------|
| MOT test number | 908997451378 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-10 |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #8 | 2022-10-03 12:38 |
|-----------------|------------------|
| MOT test number | 285239614558 |
| Result | ✓ Passed |
| | |

| MOT #7 | | 2022-10-03 09:54 |
|-----------------|--|------------------|
| MOT test number | er | 326874881151 |
| Result | | X Failed |
| DANGEROUS | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #6 | 2021-09-28 11:50 |
|-----------------|------------------|
| MOT test number | 598531512135 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



(ii))

HY66VFE

report date: 2024-03-28

2021-09-18 09:33 **MOT #5** 160522698274 **MOT** test number Result × Failed **MAJOR** Horn sound not in accordance with requirements (7.7 (c)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e)) **MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

| MOT #4 | 2020-09-21 14:20 |
|-------------------------|---|
| MOT test number | 868620523370 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2020-09-21 14:20 |
| MOT test number | 436271291225 |
| Result | X Failed |
| Pass with rectification | Nearside Side repeater incorrect colour (4.4.3 (a)) |
| Pass with rectification | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Pass with rectification | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| Pass with rectification | Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) |

| MOT #2 | 2019-09-25 09:29 |
|-----------------|------------------|
| MOT test number | 789121536903 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/12



position lamps (4.7.2 (a))

HY66VFE

report date: 2024-03-28

MOT #1

MOT test number

486217519155

Result

Pass with rectification

Offside Rear Registration plate lamp does not illuminate simultaneously with the


Pass with rectification Nearside Rear Lower Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Nearside Rear Lower Position lamp not working marker light (4.2.1 (a) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 186 |
| MOT expiry date | 10 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e union mestery | |
|---|---|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in | |
| *************************************** | |
| | |
| *************************************** | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Correct registration | NK NA |
| Plate since | |
| Current registration | UK NE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2016-10-07 |
| Last registration | 2023-10-11 |
| Complete history | See info |



| Registration #1 | 2016-10-07 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2019-09-25 | 37.621 mi |
| Registration #3 | 2019-09-25 | 37.621 mi |
| Registration #4 | 2020-09-21 | 58.026 mi |
| Registration #5 | 2020-09-21 | 58.026 mi |
| Registration #6 | | 0.00 44 |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 0.00 44 |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.777 au |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 2470 mm |
|---------------------|---------|
| Height | 2488 mm |
| Length | 6198 mm |
| Kerb weight | 1970 kg |
| Max. allowed weight | 3500 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | C226500 |

CarCheck.co.uk page 12/12