



RENAULT

LAIUDO


report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC GRAND DYNAMIQUE TOMTOM DCI EDC
Colour	Black
Year of manufacture	2011
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 BHP
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D





MOT history

MOT expiry date	2021-08-27
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #9	2020-08-28 10:42
MOT test number	310749799391
Result	✓ Passed
Next expiry date	2021-08-27

MOT #8	2019-03-30 10:14
MOT test number	449570627237
Result	✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Front Child Seat fitted not allowing full inspection of adult belt

MOT #7	2017-11-22 10:59
MOT test number	932230772430
Result	✓ Passed
Advice	Both front tyres heavily worn on edges
Advice	Rear brake pads wearing low

**MOT #6** 2017-11-22 10:59**MOT test number** 132961369905**Result** ✗ Failed**Advice** Both front tyres heavily worn on edges**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Rear brake pads wearing low**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-10-05 10:34**MOT test number** 405812445731**Result** ✓ Passed**Advice** Nearside front tyre wearing low**Advice** Offside Rear Tyre worn close to the legal limit recommend replacement (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit recommend replacement (4.1.E.1)**MOT #4** 2016-10-01 12:58**MOT test number** 419621828304**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit recommend replacement (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit recommend replacement (4.1.E.1)**Advice** Nearside front tyre wearing low

**MOT #3** 2015-09-27 10:28**MOT test number** 568349753619**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Recommend replacement (4.1.E.1)**MOT #2** 2015-09-27 10:28**MOT test number** 825589271351**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit Recommend replacement (4.1.E.1)**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #1** 2014-09-12 09:53**MOT test number** 146975254285**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	LA11UDO
Plate since	2019-03-28
Current registration	LA11UDO
Plate since	2019-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2011-04-08
Last registration	2020-08-28
Complete history	See info



Registration #1	2011-04-08	27 mi
Registration #2	2014-09-12	44.282 mi
Registration #3	2015-09-27	53.403 mi
Registration #4	2015-09-27	53.403 mi
Registration #5	2016-10-01	62.866 mi
Registration #6	2019-05-29	75.277 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2020-08-28	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2077 mm
Height	1645 mm
Length	4560 mm
Wheel base	2770 mm
Kerb weight	1523 kg
Max. allowed weight	2153 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number D016772