



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC
Colour	Black
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-11
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	38
Total items failed	13

MOT #17	2024-01-12 12:26
MOT test number	694446682726
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Central Exhaust support corroded & broken off
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust support corroded & broken off
Advice	Exhaust heat shield insecure

MOT #16	2024-01-11 12:06
MOT test number	881602987511
Result	✗ Failed
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Central Exhaust support corroded & broken off
Fail	Nearside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Rear Exhaust support corroded & broken off
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust heat shield insecure

**MOT #15**

2023-01-10 11:12

MOT test number

433400006778

Result

✓ Passed

- Advice** Coolant low
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14

2022-01-07 13:59

MOT test number

787905081722

Result

✓ Passed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Central Exhaust mounting defective hanger broke (6.1.2 (a))
- Advice** Items removed from driver's view prior to test
- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear pipe (1.1.11 (c))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #13

2021-01-06 15:57

MOT test number

911631787427

Result

✓ Passed

- Advice** Rear rear exhaust silencer outer skin corroded/cracking
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened on inner edge (1.1.14 (a) (ii))
- Advice** Front front wiper blades slight deterioration

**MOT #12** 2020-01-09 15:48**MOT test number** 978725336248**Result** ✓ Passed**Advice** Some suspension components slightly corroded**MOT #11** 2019-01-11 16:46**MOT test number** 591369095722**Result** ✓ Passed**MOT #10** 2019-01-08 12:54**MOT test number** 946459676271**Result** ✗ Failed**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on 1.6mm limit (5.2.3 (e))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-12-20 12:03**MOT test number** 468141614191**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Engine management light on

**MOT #8** 2017-12-20 10:23**MOT test number** 658978324277**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Engine management light on**MOT #7** 2017-01-04 10:45**MOT test number** 803742957726**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Engine management light on.**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2016-01-06 12:51**MOT test number** 352787897497**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened Both (3.5.1i)**Advice** EML Illuminated**MOT #5** 2014-12-19 14:27**MOT test number** 705133754399**Result** ✓ Passed

**MOT #4** 2014-01-09 13:59**MOT test number** 546559204000**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-01-08 13:15**MOT test number** 137068904006**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #2** 2013-07-24 13:57**MOT test number** 905425503296**Result** ✓ Passed**MOT #1** 2013-07-24 13:38**MOT test number** 285265203230**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 January 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SG60SVZ
Plate since	2019-03-29
Current registration	SG60SVZ
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-17
Last registration	2024-01-12
Complete history	See info



Registration #1	2010-09-17	29 mi
Registration #2	2013-07-24	12.920 mi
Registration #3	2013-07-24	12.920 mi
Registration #4	2014-01-08	13.431 mi
Registration #5	2014-01-09	13.431 mi
Registration #6	2014-12-19	22.146 mi
Registration #7	2016-01-06	28.115 mi
Registration #8	2017-01-04	33.588 mi
Registration #9	2017-12-20	37.633 mi
Registration #10	2017-12-20	37.633 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi
Registration #18	2019-05-29	55.277 mi
Registration #19	2019-05-29	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AP59922