



RENAULT

GF570NC

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE NON FAP DCI 130
Colour	Gold
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	300 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg




LABEL UNKNOWN



Internet history

Entry 6


Date	2021-12-14
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 5


Date	2021-12-05
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 4

Date	2021-12-05
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)

Entry 3


Date	2021-11-05
------	------------

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date


2021-11-05

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date


2021-10-08

Pictures

20

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #18	2022-01-05 15:23
MOT test number	599271245390
Result	✓ Passed
Next expiry date	2023-01-04
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17	2021-12-22 10:21
MOT test number	225165555800
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #16	2020-12-05 11:53
MOT test number	159741205297
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2019-12-17 14:34
MOT test number	245340023625
Result	✓ Passed

**MOT #14** 2018-11-05 14:23**MOT test number** 507993049893**Result** ✓ Passed**MOT #13** 2018-11-02 12:08**MOT test number** 983592457008**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #12** 2017-11-04 10:48**MOT test number** 810377555874**Result** ✓ Passed**MOT #11** 2016-11-04 11:52**MOT test number** 160887690296**Result** ✓ Passed**Advice** Clutch pedal anti-slip provision missing**Advice** Rear exhaust rubber mount damaged, but system is adequately supported**MOT #10** 2016-11-04 10:35**MOT test number** 694390936634**Result** ✗ Failed**Advice** Clutch pedal anti-slip provision missing**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear exhaust rubber mount damaged, but system is adequately supported

**MOT #9** 2015-11-07 16:07**MOT test number** 727377155853**Result** ✓ Passed**MOT #8** 2014-10-22 17:23**MOT test number** 536665894280**Result** ✓ Passed**MOT #7** 2014-10-22 12:40**MOT test number** 719005194237**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-11-05 15:08**MOT test number** 176439903310**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2013-11-05 09:22**MOT test number** 465549503429**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Play in steering rack inner joint(s)**MOT #4** 2012-10-20 10:17**MOT test number** 399104192486**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** All brake discs slightly worn**MOT #3** 2011-11-01 15:35**MOT test number** 715955001399**Result** ✓ Passed**MOT #2** 2011-11-01 09:57**MOT test number** 846755301306**Result** ✗ Failed**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2010-10-22 13:14**MOT test number** 110165090227**Result** ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2007-11-07
Last registration	2022-01-05
Complete history	See info



Registration #1	2007-11-07	16 mi
Registration #2	2010-10-22	26.825 mi
Registration #3	2011-11-01	35.245 mi
Registration #4	2011-11-01	35.245 mi
Registration #5	2012-10-20	47.436 mi
Registration #6	2013-11-05	60.320 mi
Registration #7	2013-11-05	60.321 mi
Registration #8	2014-10-22	72.223 mi
Registration #9	2014-10-22	72.223 mi
Registration #10	2015-11-07	80.037 mi
Registration #11	2016-11-04	82.824 mi
Registration #12	2016-11-04	82.824 mi
Registration #13	2017-11-04	91.115 mi
Registration #14	2018-11-04	91.115 mi
Registration #15	2018-11-04	91.115 mi
Registration #16	2018-11-04	91.115 mi
Registration #17	2018-11-04	91.115 mi
Registration #18	2018-11-04	91.115 mi
Registration #19	2018-11-04	91.115 mi
Registration #20	2018-11-04	91.115 mi
Registration #21	2018-11-04	91.115 mi
Registration #22	2018-11-04	91.115 mi
Registration #23	2018-11-04	91.115 mi
Registration #24	2018-11-04	91.115 mi
Registration #25	2018-11-04	91.115 mi



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1404 mm
Length	4355 mm
Wheel base	2522 mm
Kerb weight	1430 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	C034488