



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI 16V E4
Colour	Silver
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	175 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-09-29
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-25
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #17 2023-10-26 10:28

MOT test number 669703377842

Result ✓ Passed

Next expiry date 2024-10-25

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material at fuel tank area (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2022-10-08 08:04

MOT test number 857636360684

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner faces (1.1.14 (a) (ii))

MOT #15 2021-10-09 10:59

MOT test number 798709744577

Result ✓ Passed

MOT #14 2020-10-20 09:39

MOT test number 789245493319

Result ✓ Passed

**MOT #13** 2019-10-07 15:40**MOT test number** 606615046343**Result** ✓ Passed**Advice** Coolant leak**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2019-10-07 09:53**MOT test number** 458771387956**Result** ✗ Failed**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Coolant leak**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #11** 2018-10-03 09:51**MOT test number** 709961733636**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**MOT #10** 2017-10-17 08:17**MOT test number** 315302346429**Result** ✓ Passed**MOT #9** 2016-10-04 07:59**MOT test number** 364504735245**Result** ✓ Passed



MOT #8	2015-10-07 12:17
MOT test number	418935541901
Result	✓ Passed
Advice	Offside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)
Advice	Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)

MOT #7	2014-07-31 11:50
MOT test number	846112914284
Result	✓ Passed
Notice	Front exhaust flexi joint deteriorated
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Notice	Oil leak
Advice	Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #6	2014-07-30 14:56
MOT test number	355781514243
Result	✗ Failed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Notice	Front exhaust flexi joint deteriorated
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
Notice	Oil leak

MOT #5	2013-07-10 16:08
MOT test number	939171093152
Result	✓ Passed

**MOT #4** 2013-07-10 14:21**MOT test number** 957841493112**Result** ✗ Failed**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #3** 2012-06-28 13:12**MOT test number** 788120882132**Result** ✓ Passed**MOT #2** 2011-06-15 14:15**MOT test number** 466956461139**Result** ✓ Passed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #1** 2010-06-25 15:00**MOT test number** 272216070425**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
25 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01
Number of owners	1
Current owner since	2019-01-01
Previous owner since	2019-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FG07LDX
Plate since	2019-01-01
Current registration	 FG07LDX
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-11
Last registration	2023-10-26
Complete history	See info



Registration #1	2007-06-11	8 mi
Registration #2	2010-06-25	57.926 mi
Registration #3	2011-06-15	71.998 mi
Registration #4	2012-06-28	85.020 mi
Registration #5	2013-07-10	97.841 mi
Registration #6	2013-07-10	97.841 mi
Registration #7	2014-07-30	111.853 mi
Registration #8	2014-07-31	111.853 mi
Registration #9	2015-10-07	126.037 mi
Registration #10	2016-10-04	138.155 mi
Registration #11	2016-10-04	138.155 mi
Registration #12	2016-10-04	138.155 mi
Registration #13	2016-10-04	138.155 mi
Registration #14	2016-10-04	138.155 mi
Registration #15	2016-10-04	138.155 mi
Registration #16	2016-10-04	138.155 mi
Registration #17	2016-10-04	138.155 mi
Registration #18	2016-10-04	138.155 mi
Registration #19	2016-10-04	138.155 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2033 mm
Height	1467 mm
Length	4249 mm
Wheel base	2614 mm
Kerb weight	1248 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KL2939