



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-08
Pictures	2
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-04
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	45
Total items failed	10

MOT #15	2024-02-05 08:52
MOT test number	959433427992
Result	✓ Passed
Next expiry date	2025-02-04
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #14**

2022-12-07 13:01

MOT test number

162623385332

Result

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Items removed from driver's view prior to test hanging from mirror
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13

2021-12-08 14:59

MOT test number

421167796375

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

MOT #12

2020-12-02 11:55

MOT test number

104747262188

Result

✓ Passed

MOT #11

2020-12-02 09:07

MOT test number

669325523067

Result

✗ Failed

- MAJOR** Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt o/s/f inner (6.1.7 (g) (ii))

**MOT #10** 2019-05-21 11:46**MOT test number** 826065975651**Result** ✓ Passed

- Advice** Nearside repeater lens is missing
- Advice** Both front tyres are wearing on inner edges
- Advice** Both rear tyres are cracking in tread

MOT #9 2018-05-15 13:43**MOT test number** 241687874322**Result** ✓ Passed

- Advice** Engine cover and under trays are fitted
- Advice** Offside rear tyre is cracking in tread

MOT #8 2018-05-15 11:15**MOT test number** 126528568252**Result** ✗ Failed

- Advice** Engine cover and under trays are fitted
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Rear Upper Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside rear tyre is cracking in tread
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #7 2017-05-26 15:38**MOT test number** 701552847551**Result** ✓ Passed



MOT #6	2017-05-26 11:09
MOT test number	897468704768
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5	2016-06-02 15:48
MOT test number	753015009367
Result	✓ Passed
Advice	Nearside front tyre has a nail in
Advice	Under trays fitted
Advice	Offside front tyre wearing on inner edge
Advice	Engine covers fitted
Advice	Offside rear tyre is cracking and wearing on inner edge

**MOT #4**

2016-06-02 13:48

MOT test number

316418338616

Result**✗ Failed**

- Advice** Offside rear tyre is cracking and wearing on inner edge
- Advice** Nearside front tyre has a nail in
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Under trays fitted
- Advice** Offside front tyre wearing on inner edge
- Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Engine covers fitted
- Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #3

2015-06-03 15:38

MOT test number

775124855192

Result**✓ Passed**

- Notice** Offside rear inner brake pad getting low
- Notice** Front brake pads getting low

MOT #2

2014-05-30 14:31

MOT test number

466660054179

Result**✓ Passed**

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components



MOT #1	2014-05-30 10:29
MOT test number	288490854129
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AD10HXX
Plate since	2024-03-28
Current registration	AD10HXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-16
Last registration	2024-02-05
Complete history	See info



Registration #1	2010-08-16	24 mi
Registration #2	2014-05-30	32.718 mi
Registration #3	2014-05-30	32.718 mi
Registration #4	2015-06-03	39.980 mi
Registration #5	2016-06-02	46.927 mi
Registration #6	2016-06-02	46.927 mi
Registration #7	2017-05-26	63.382 mi
Registration #8	2017-05-26	63.382 mi
Registration #9	2018-05-15	71.843 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1361361