



DE57UYG


report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | JAGUAR |
| Model | X-TYPE SE |
| Colour | Grey |
| Year of manufacture | 2007 |
| Top speed | 125 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 129 BHP |
| Max. torque | 331 Nm at 1.800 rpm |
| Engine capacity | 1.988 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 49.6 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-20 |
| Pictures | 32 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-26 |
| MOT pass rate | 93 % |
| MOT passed | 14 |
| Failed MOT tests | 1 |
| Total advice items | 19 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #15 | 2023-07-14 08:20 |
| MOT test number | 233191290378 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-26 |

| | |
|-----------------|------------------|
| MOT #14 | 2022-07-27 08:37 |
| MOT test number | 147001746927 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #13 | 2021-07-15 08:43 |
| MOT test number | 280770062484 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #12 | 2020-06-29 11:11 |
| MOT test number | 992401788653 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #11 | 2019-07-12 12:25 |
| MOT test number | 421335869049 |
| Result | ✓ Passed |

**MOT #10** 2018-07-17 10:09**MOT test number** 423780329602**Result** ✓ Passed

- Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2017-09-21 09:52**MOT test number** 202026180320**Result** ✓ Passed

- Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

MOT #8 2016-09-20 11:03**MOT test number** 426364585797**Result** ✓ Passed**MOT #7** 2015-09-18 09:56**MOT test number** 698536583854**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement NS and OS (2.4.G.2)
- Advice** Engine covers and under trays fitted
- Advice** Front Tyre worn close to the legal limit NS and OS (4.1.E.1)



| | |
|------------------------|---|
| MOT #6 | 2014-09-10 12:34 |
| MOT test number | 976313754212 |
| Result | ✓ Passed |
| Advice | Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) |
| Advice | Front registration plate deteriorated but not likely to be misread (6.3.1d) |

| | |
|------------------------|--|
| MOT #5 | 2013-09-04 13:59 |
| MOT test number | 245047343200 |
| Result | ✓ Passed |
| Advice | Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2) |
| Advice | Front registration plate delaminated but not likely to be misread (6.3.1d) |
| Advice | Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2) |
| Advice | Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a) |

| | |
|--------------------------------|--|
| MOT #4 | 2013-09-04 13:59 |
| MOT test number | 577467543242 |
| Result | ✗ Failed |
| Pass with rectification | Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b) |
| Advice | Front registration plate delaminated but not likely to be misread (6.3.1d) |
| Advice | Offside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2) |
| Pass with rectification | Offside Headlamp aim too low (1.8) |
| Advice | Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a) |
| Advice | Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2) |
| Pass with rectification | Nearside Headlamp aim too low (1.8) |



| | |
|-----------------|------------------|
| MOT #3 | 2012-09-27 17:03 |
| MOT test number | 316461572445 |
| Result | ✓ Passed |
| MOT #2 | 2011-10-25 17:44 |
| MOT test number | 215238891214 |
| Result | ✓ Passed |
| MOT #1 | 2010-10-25 12:11 |
| MOT test number | 854548390273 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
26 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 26 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,200 |
| Auction value | £ 19,200 |
| Average private trade value | £ 19,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | DE57UYG |
| Plate since | 2019-03-28 |
| Current registration | DE57UYG |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2007-11-01 |
| Last registration | 2023-07-14 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-11-01 | 16 mi |
| Registration #2 | 2010-10-25 | 30.233 mi |
| Registration #3 | 2011-10-25 | 40.191 mi |
| Registration #4 | 2012-09-27 | 49.177 mi |
| Registration #5 | 2013-09-04 | 52.265 mi |
| Registration #6 | 2014-09-10 | 55.794 mi |
| Registration #7 | 2015-09-18 | 59.435 mi |
| Registration #8 | 2016-09-20 | 76.226 mi |
| Registration #9 | 2016-09-20 | 76.226 mi |
| Registration #10 | 2016-09-20 | 76.226 mi |
| Registration #11 | 2016-09-20 | 76.226 mi |
| Registration #12 | 2016-09-20 | 76.226 mi |
| Registration #13 | 2016-09-20 | 76.226 mi |
| Registration #14 | 2016-09-20 | 76.226 mi |
| Registration #15 | 2016-09-20 | 76.226 mi |
| Registration #16 | 2016-09-20 | 76.226 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2003 mm |
| Height | 1392 mm |
| Length | 4672 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1502 kg |
| Max. allowed weight | 2015 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 61 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 0709200030106G |