



AF6IYU0

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SE TSI
Colour	Grey
Year of manufacture	2011
Top speed	135 mph
0 - 100 km/h	8.8 seconds
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 kW / 161 HP / 158 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	24
Total items failed	7

MOT #12	2023-05-05 13:19
MOT test number	563834146172
Result	✓ Passed
Next expiry date	2024-05-14
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11	2022-04-20 15:10
MOT test number	988560890746
Result	✓ Passed
Advice	Undertrays fitted

MOT #10	2022-03-23 11:47
MOT test number	550621976786
Result	✗ Failed
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside parking brake lever not returning to stop/start position
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Under trays fitted to vehicle
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9** 2021-05-15 10:34**MOT test number** 957933990020**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Under trays fitted to vehicle**Advice** Nearside parking brake lever on caliper not fully returning to stop/start position**MOT #8** 2020-05-06 13:36**MOT test number** 182374716865**Result** ✓ Passed**Advice** Offside Front slight damage to inside of alloy wheel rim**MOT #7** 2020-05-04 10:44**MOT test number** 894797795814**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear tyre worn on inner edge and cracking in tread**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front slight damage to inside of alloy wheel rim**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2019-04-02 09:10**MOT test number** 997454614887**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres slight cracking in tread and worn on inner edges**MOT #5** 2019-04-01 11:33**MOT test number** 885087709257**Result** ✗ Failed**Advice** Both rear tyres slight cracking in tread and worn on inner edges**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-03-27 16:05**MOT test number** 118612118159**Result** ✓ Passed**MOT #3** 2017-03-13 14:30**MOT test number** 739067214191**Result** ✓ Passed



MOT #2	2015-09-11 07:34
MOT test number	340937645076
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	REAR TYRES PERISHED.
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	FRONT TYRES PART WORN.

MOT #1	2014-09-01 13:54
MOT test number	667424244212
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
14 May 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-12
Last registration	2023-05-05
Complete history	See info



Registration #1	2011-09-12	7 mi
Registration #2	2014-09-01	25.892 mi
Registration #3	2015-09-11	36.650 mi
Registration #4	2017-03-13	52.522 mi
Registration #5	2018-03-27	62.815 mi
Registration #6	2019-04-01	68.686 mi
Registration #7	2019-04-02	68.686 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2009 mm
Height	1444 mm
Length	4423 mm
Wheel base	2578 mm
Kerb weight	1505 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CAV 261545