



R88FLS

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | BMW |
| Model | X6 XDRIVE35D |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 147 mph |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 282 BHP |
| Max. torque | 580 Nm at 1.750 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 26.9 mpg |
| Consumption extra urban | 39.8 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 220 g/km |
| CO2 label | K |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-10 |
| MOT pass rate | 71 % |
| MOT passed | 12 |
| Failed MOT tests | 5 |
| Total advice items | 30 |
| Total items failed | 19 |

| | |
|------------------|---|
| MOT #17 | 2023-10-09 16:53 |
| MOT test number | 615991247752 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-10 |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #16 | 2022-10-11 15:26 |
| MOT test number | 212445806369 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #15 | 2021-10-10 13:17 |
| MOT test number | 724280588192 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

**MOT #14**

2021-10-10 13:17

MOT test number

786384868172

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #13**

2021-10-09 14:13

MOT test number

965407198418

Result**✗ Failed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tread depth getting low 3mm (5.2.3 (e))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt outer (5.3.4 (b) (ii))**Advice** Signs of engine oil leak**Advice** Offside Rear Tyre worn close to legal limit/worn on edge tread depth getting low 3mm (5.2.3 (e))**Advice** Engine under tray cover fitted not allowing full inspection**Advice** Items removed from driver's view prior to test**MOT #12**

2020-10-01 10:52

MOT test number

481701332300

Result**✓ Passed****Advice** Front Bonnet primary retaining device slightly deteriorated (3.1 (c))

**MOT #11**

2020-09-29 13:03

MOT test number

661423132466

Result**✗ Failed**

- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Bonnet primary retaining device insecure (3.1 (c))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Front Registration plate missing (0.1 (a))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #10

2019-09-18 14:56

MOT test number

733265837088

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2018-09-07 12:35

MOT test number

648325052694

Result**✓ Passed**

**MOT #8** 2017-08-30 13:39**MOT test number** 963217258067**Result** ✓ Passed**MOT #7** 2016-09-01 14:58**MOT test number** 454312468797**Result** ✓ Passed**Advice** Front and rear brake pads very low just pass mot**MOT #6** 2015-09-03 00:00**MOT test number** 734904593639**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-12-19 13:49**MOT test number** 586933854351**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2014-12-19 11:57**MOT test number** 187743954305**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Rear registration plate character(s) laid out in an incorrect format (6.3.4f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Headlamp cleaning device inoperative (1.7.2)
- Fail** Front registration plate missing (6.3.1a)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)

MOT #3 2013-09-24 10:53**MOT test number** 218407463216**Result** ✓ Passed**MOT #2** 2012-09-25 09:51**MOT test number** 238429262215**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|---|
| MOT #1 | 2012-09-25 08:48 |
| MOT test number | 835409362299 |
| Result | ✗ Failed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Fail | Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
10 October 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 33 |
| MOT expiry date | 10 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 0 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.


| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2009-09-26 |
| Last registration | 2023-10-09 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2009-09-26 | 21 mi |
| Registration #2 | 2012-09-25 | 44.761 mi |
| Registration #3 | 2012-09-25 | 44.761 mi |
| Registration #4 | 2013-09-24 | 60.536 mi |
| Registration #5 | 2014-12-19 | 81.633 mi |
| Registration #6 | 2014-12-19 | 81.633 mi |
| Registration #7 | 2015-09-03 | 95.506 mi |
| Registration #8 | 2016-09-01 | 105.568 mi |
| Registration #9 | 2017-08-30 | 117.624 mi |
| Registration #10 | 2018-08-29 | 131.577 mi |
| Registration #11 | 2019-08-28 | 145.530 mi |
| Registration #12 | 2020-08-27 | 159.483 mi |
| Registration #13 | 2021-08-26 | 173.436 mi |
| Registration #14 | 2022-08-25 | 187.389 mi |
| Registration #15 | 2023-08-24 | 201.342 mi |
| Registration #16 | 2024-08-23 | 215.295 mi |
| Registration #17 | 2025-08-22 | 229.248 mi |
| Registration #18 | 2026-08-21 | 243.201 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1983 mm |
| Height | 1690 mm |
| Length | 4877 mm |
| Wheel base | 2933 mm |
| Kerb weight | 2110 kg |
| Max. allowed weight | 2710 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 85 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 4 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 23237204 |