



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 VTR
Colour	Silver
Year of manufacture	2009
Top speed	105 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-22
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-29
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	22
Total items failed	22

MOT #19	2023-07-03 13:08
MOT test number	451002569798
Result	✓ Passed
Next expiry date	2024-07-29
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18	2022-06-30 09:08
MOT test number	930107774787
Result	✓ Passed

MOT #17	2021-07-29 14:13
MOT test number	403147483938
Result	✓ Passed

**MOT #16** 2021-07-29 12:05**MOT test number** 363072661385**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MOT #15** 2020-07-30 10:44**MOT test number** 928927329456**Result** ✓ Passed**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #14** 2020-07-30 10:44**MOT test number** 694428432053**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))



MOT #132019-07-26 09:19

MOT test number383578039091

Result

✓ Passed

- Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Rear Exhaust mounting defective (6.1.2 (a))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2019-07-24 11:27

MOT test number

538316553889

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11

2018-07-25 13:35

MOT test number

912265568534

Result**✓ Passed**

**MOT #10** 2018-07-25 13:35**MOT test number** 444468568841**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #9** 2017-06-22 11:03**MOT test number** 498721706710**Result** ✓ Passed**MOT #8** 2017-06-14 14:49**MOT test number** 153150478956**Result** ✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Direction indicator not working (1.4.A.2c)
- Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2016-10-21 09:24**MOT test number** 534582706273**Result** ✓ Passed**MOT #6** 2016-10-21 09:24**MOT test number** 775152456976**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint is insecure (2.5.C.1b)



MOT #5	2015-10-23 09:45
---------------	------------------

MOT test number	904898163246
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-10-29 14:48
---------------	------------------

MOT test number	458982104467
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-09-19 11:18
---------------	------------------

MOT test number	965232263242
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-09-19 10:23
---------------	------------------

MOT test number	455042063210
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #1	2012-09-19 10:25
---------------	------------------

MOT test number	305513962482
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-17
Last registration	2023-07-03
Complete history	See info



Registration #1	2009-09-17	24 mi
Registration #2	2012-09-19	19.733 mi
Registration #3	2013-09-19	26.091 mi
Registration #4	2013-09-19	26.091 mi
Registration #5	2014-10-29	29.457 mi
Registration #6	2015-10-23	32.855 mi
Registration #7	2016-10-21	37.341 mi
Registration #8	2016-10-21	37.341 mi
Registration #9	2017-06-14	38.995 mi
Registration #10	2017-06-22	38.997 mi
Registration #11	2018-07-25	45.651 mi
Registration #12	2019-06-20	51.317 mi
Registration #13	2019-06-20	51.317 mi
Registration #14	2019-06-20	51.317 mi
Registration #15	2019-06-20	51.317 mi
Registration #16	2019-06-20	51.317 mi
Registration #17	2019-06-20	51.317 mi
Registration #18	2019-06-20	51.317 mi
Registration #19	2019-06-20	51.317 mi
Registration #20	2019-06-20	51.317 mi
Registration #21	2019-06-20	51.317 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	990 kg
Max. allowed weight	1362 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FST36122073