





report date: 2024-03-28

## General information

| Make                | CITROEN                     |
|---------------------|-----------------------------|
| Model               | XSARA HDI EXCLUSIVE PICASSO |
| Colour              | Grey                        |
| Year of manufacture | 2003                        |
| Top speed           | 109 mph                     |
| 0 - 60 mph          | 12.6 seconds                |
| Gearbox             | 5 speed Manual              |

## Engine & fuel consumption

| Power                   | 90 BHP              |
|-------------------------|---------------------|
| Max. torque             | 205 Nm at 1.900 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 40.4 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 51.4 mpg            |
| CO2 emission            | 147 g/km            |
| CO2 label               | F                   |



CarCheck.co.uk page 1/15



report date: 2024-03-28

## Internet history

## Entry 1

Date 2021-06-10

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

| MOT expiry date    | 2021-10-14 |
|--------------------|------------|
| MOT pass rate      | 71 %       |
| MOT passed         | 15         |
| Failed MOT tests   | 6          |
| Total advice items | 24         |
| Total items failed | 11         |

| MOT #21                 |   | 2020-09-22 14:37      |
|-------------------------|---|-----------------------|
| MOT test                | number  | 542141418646          |
| Result                  |   | ✓ Passed              |
| Next exp                | iry date  | 2021-10-14            |
| Advice                  | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                      |                       |
| Advice                  | Front Brake pipe corroded, covered in grease or other material To rear (1.                  | 1.11 (c))             |
| Advice                  | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                   |                       |
| <b>Advice</b> excessive | Offside Outer Suspension component mounting prescribed area is corrode Sill (5.3.6 (a) (i)) | ed but not considered |
| Advice                  | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                       |                       |

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #20** 2020-09-22 13:45

**MOT test number** 367712217037

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Front Brake pipe corroded, covered in grease or other material To rear (1.1.11 (c))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Outer Suspension component mounting prescribed area is corroded but not considered excessive Sill (5.3.6 (a) (i))

**MOT #19** 2019-10-15 10:38

**MOT test number** 359938104194

Result \( \sqrt{Passed} \)

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #18 2019-02-07 16:33

**MOT test number** 582781111521

Result 

Passed

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #17** 2019-02-07 10:47 660753381735 **MOT test number** Result × Failed Fail Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii)) Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Advice **Advice** Nearside Front Outer Direction indicator slightly discoloured (4.4.3 (a)) Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii)) Fail Offside Headlamp aim too far to the left (4.1.2 (a)) **Advice** Offside Front Outer Direction indicator slightly discoloured (4.4.3 (a))

| MOT #16   | 2018-02-09 13:07 |
|---|------------------|
| MOT test number                                   | 716023624375     |
| Result  | ✓ Passed         |
| Advice Front coil spring corroded both (2.4.C.1b) |                  |

| MOT #15  | 2017-04-28 16:18 |
|--|------------------|
| MOT test number                                  | 984601657769     |
| Result   | √ Passed         |
|  |                  |
| MOT #14  | 2017-04-28 10:55 |
| MOT test number                                  | 728540405625     |
| Result   | <b>×</b> Failed  |
| Fail Offside Rear Stop lamp not working (1.2.1b) |                  |

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #13

MOT test number

626238763698

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear childseat fit

MOT #12

MOT test number

Result

Notice Spare tyre defective

 MOT #11
 2013-12-17 09:27

 MOT test number
 345381053390

 Result
 ✓ Passed

MOT test number

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9

MOT test number

427183532357

Result

√ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

| MOT #8  | 2011-05-25 17:57 |
|---|------------------|
| MOT test number   | 408595141184     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #7  | 2010-08-27 12:48 |
| MOT test number   | 844289630220     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #6  | 2010-08-27 09:32 |
| MOT test number   | 612549730221     |
| Result  | <b>×</b> Failed  |
| Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) |                  |

| MOT #5   | 2009-09-03 16:44 |
|--|------------------|
| MOT test number  | 564716649244     |
| Result   | <b>✓</b> Passed  |
|  |                  |
| MOT #4   | 2009-09-03 14:41 |
| MOT test number  | 473356249261     |
| Result   | <b>×</b> Failed  |
| Fail Front Windscreen washer provides insufficient washer liquid (8.2.3) |                  |

| MOT #3   |  | 2008-08-21 10:01 |
|----------|--|------------------|
| MOT test | number   | 590524938272     |
| Result   |  | ✓ Passed         |
| Notice   | Child seat fitted not allowing full inspection of adult belt |                  |
| Notice   | Nail in offside rear tyre                                    |                  |

CarCheck.co.uk page 7/15



MOT #2

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

 MOT #1
 2006-09-05 16:38

 MOT test number
 784248946222

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



## Tax & MOT check

Tax expired: 14 October 2021



Expired:

X MOT

Expired: 14 October 2021

| Tax status       | Expired at 14 October 2021 |
|------------------|----------------------------|
| Days left        | 927 days too late          |
| MOT expiry date  | 14 October 2021            |
| Full MOT history | See MOT history            |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 9/15



report date: 2024-03-28

## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

## Owner history

| ,  |           |      |
|--|-----------|------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full |           | ROEN |
| ***************************************  |           |      |
|  |           |      |
| ***************************************  |           |      |
|  |           |      |
|  |           |      |
|  |           |      |
|  | More info | >    |
| Plate changes  |           |      |
| See in this check if this CITROEN had different number plates.   |           |      |
| Number of plates   |           |      |
| Current registration   | NK SIE    |      |
| Plate since  |           |      |
| Current registration   | NK NK     |      |
| Plate since  |           |      |
|  | More info | >    |

CarCheck.co.uk page 12/15



report date: 2024-03-28

## Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 13/15



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 23         |
| First mileage registration | 2003-09-03 |
| Last registration          | 2020-09-22 |
| Complete history           | See info   |



| Registration #1  | 2003-09-03 | 26 mi     |
|------------------|------------|-----------|
| Registration #2  | 2006-09-05 | 19.488 mi |
| Registration #3  | 2007-08-29 | 24.978 mi |
| Registration #4  | 2008-08-21 | 30.197 mi |
| Registration #5  | 2009-09-03 | 36.397 mi |
| Registration #6  | 2009-09-03 | 36.397 mi |
| Registration #7  | 2010-08-27 | 41.472 mi |
| Registration #8  | 2010-08-27 | 41.472 mi |
| Registration #9  | 2011-05-25 | 45.175 mi |
| Registration #10 | 2012-11-28 | 61.490 mi |
| Registration #11 | 2013-12-12 | 71.973 mi |
| Registration #12 | 2013-12-17 | 72.188 mi |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11.777 es |
| Registration #16 |            | 11.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 11.777 es |
| Registration #19 |            | 11.777 es |
| Registration #20 |            | D.777 es  |
| Registration #21 |            | 11.777 es |
| Registration #22 |            | D.777 es  |
| Registration #23 |            | 0.00 es   |

More info >

CarCheck.co.uk page 14/15



# Safety ratings

| NCAP rating | *** |  |
|-------------|-----|--|
|             |     |  |

**Video** <u>see crash video</u>

# Dimensions & weight

| Width       | 1752 mm |
|-------------|---------|
| Height      | 1625 mm |
| Length      | 4267 mm |
| Wheel base  | 2760 mm |
| Kerb weight | 1300 kg |

# Additional information

| Fuel tank capacity | 60 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of axles    | 2                |
| Engine number      | DYLP3037355      |

CarCheck.co.uk page 15/15