



LRIINJF

report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	Black
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-03
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-10-11
<b>MOT pass rate</b>	82 %
<b>MOT passed</b>	9
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	22
<b>Total items failed</b>	6

**MOT #11** 2022-10-12 15:40**MOT test number** 552517563023**Result** ✓ Passed**Next expiry date** 2023-10-11**Minor** Offside Front Outer Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10** 2021-10-07 16:19**MOT test number** 771302503802**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged inner side wall (5.2.3 (d) (ii))**Minor** Offside Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9**

2021-10-06 11:23

**MOT test number**

262844007696

**Result****✗ Failed****Fail**

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Minor**

Offside Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

**Fail**

Nearside Headlamp aim not tested (4.1.2 (b))

**Advice**

Nearside Rear Nail in tyre

**Fail**

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice**

Nearside Rear Tyre slightly damaged inner side wall (5.2.3 (d) (ii))

**MOT #8**

2020-09-28 11:57

**MOT test number**

162557081236

**Result****✓ Passed****Advice**

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #7**

2020-03-28 13:37

**MOT test number**

904606328279

**Result****✓ Passed****MOT #6**

2019-04-11 15:01

**MOT test number**

891456830798

**Result****✓ Passed**

**MOT #5** 2018-03-09 11:04**MOT test number** 775109503100**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2018-03-09 11:04**MOT test number** 349111640108**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2017-03-30 14:43**MOT test number** 868597105078**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-04-24 16:34**MOT test number** 866694215160**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-02-12 13:03
MOT test number	159133044446
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>LR11NJF</b>
Plate since	2024-03-28
Current registration	<b>LR11NJF</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-03
Last registration	2022-10-12
Complete history	<a href="#">See info</a>



Registration #1	2011-03-03	29 mi
Registration #2	2014-02-12	49.229 mi
Registration #3	2015-04-24	67.096 mi
Registration #4	2017-03-30	90.093 mi
Registration #5	2018-03-09	93.109 mi
Registration #6	2018-03-09	93.109 mi
Registration #7	2019-04-11	97.904 mi
Registration #8	2019-04-11	97.904 mi
Registration #9	2019-04-11	97.904 mi
Registration #10	2019-04-11	97.904 mi
Registration #11	2019-04-11	97.904 mi
Registration #12	2019-04-11	97.904 mi
Registration #13	2019-04-11	97.904 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT