



report date: 2024-03-29

General information

Make	NISSAN
Model	NV200 DCI SE
Colour	Grey
Year of manufacture	2010
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	54.3 mpg





Internet history

Entry 1

Date	2021-12-15
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-05-21
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	13

MOT #15	2023-05-22 15:26
MOT test number	168632876825
Result	✓ Passed
Next expiry date	2024-05-21
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-05-22 11:39
MOT test number	203719005418
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Windscreen washer not working (3.5 (a))
Fail	Horn not working (7.7 (a))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #13	2021-12-10 16:15
MOT test number	520724149578
Result	✓ Passed
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #12** 2020-11-25 17:33**MOT test number** 519570572678**Result** ✓ Passed**MOT #11** 2020-11-24 10:05**MOT test number** 321302069219**Result** ✗ Failed

- Fail** Horn not working (7.7 (a) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #10** 2019-05-22 15:06**MOT test number** 135434622679**Result** ✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Wheel nuts wrong type for alloy rims
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2019-05-22 07:33**MOT test number** 192747061560**Result** ✗ Failed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #8** 2018-04-09 15:59**MOT test number** 205462591185**Result** ✓ Passed**MOT #7** 2017-09-13 12:02**MOT test number** 671404672021**Result** ✓ Passed**MOT #6** 2016-10-19 09:30**MOT test number** 104975891163**Result** ✓ Passed

**MOT #5** 2015-10-30 08:48**MOT test number** 475899843551**Result** ✓ Passed**MOT #4** 2015-04-09 14:41**MOT test number** 408249995077**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-03-12 11:53**MOT test number** 928891674082**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-03-10 14:17**MOT test number** 636349364002**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**MOT #1** 2013-03-26 13:30**MOT test number** 429495983090**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
21 May 2024

**Tax status**

Valid until 1 June

**Days left**

32

**MOT expiry date**

21 May 2024

**Full MOT history**

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-31
Last registration	2023-05-22
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	17 mi
Registration #2	2013-03-26	21.752 mi
Registration #3	2014-03-10	30.590 mi
Registration #4	2014-03-12	30.686 mi
Registration #5	2015-04-09	41.456 mi
Registration #6	2015-10-30	45.724 mi
Registration #7	2016-10-19	56.363 mi
Registration #8	2017-09-13	63.195 mi
Registration #9	2018-04-09	69.710 mi
Registration #10	2019-05-22	75.227 mi
Registration #11	2019-05-22	75.227 mi
Registration #12	2019-05-22	75.227 mi
Registration #13	2019-05-22	75.227 mi
Registration #14	2019-05-22	75.227 mi
Registration #15	2019-05-22	75.227 mi
Registration #16	2019-05-22	75.227 mi
Registration #17	2019-05-22	75.227 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1269 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Number of axles	2

**Engine number**

07188D