





report date: 2024-03-29

General information

Make	BMW
Model	X5 XDRIVE30D M SPORT
Colour	Black
Year of manufacture	2015
Top speed	142 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	255 BHP
Max. torque	560 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/11



Internet history

Entry	1
-------	---

End y 1	
Date	2021-06-16
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-29
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #9	2024-04-23 16:08
MOT test number	343133775729
Result	✓ Passed
Next expiry date	2025-04-29
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT test number

Result

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Tyre has ply or cords exposed 315/35 R20 110 W XL Run Flat (5.2.3 (d) (ii))

MOT #7		2023-04-28 14:47
MOT test	number	376332654199
Result		✓ Passed
Advice	Offside Rear Nail in tyre 315-35-20 R/F	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



BD15XJE

report date: 2024-03-29

MOT #6 2022-04-27 12:04

MOT test number 725233904010

Result ✓ Passed

MOT #5 2021-04-30 13:44

MOT test number 803578427163

Result ✓ Passed

MOT #4 2021-04-29 10:44

MOT test number 496315866185

Result X Failed

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #3 2020-03-19 13:29

MOT test number 106398618611

Result \(\sqrt{Passed} \)

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2019-04-11 11:55

MOT test number 919348814760

MOT #1 2018-05-18 13:26

MOT test number 194710467159

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIX.
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-05
Last registration	2024-04-23
Complete history	See info



Registration #1	2015-06-05	11 mi
Registration #2	2018-05-18	53.291 mi
Registration #3	2019-04-11	64.092 mi
Registration #4	2020-03-19	72.878 mi
Registration #5	2021-04-29	85.780 mi
Registration #6	2021-04-30	85.780 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.771 44
Registration #11		11.777 mg

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1938 mm
Height	1762 mm
Length	4886 mm
Wheel base	2933 mm
Kerb weight	2070 kg
Max. allowed weight	2785 kg

Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles2Engine number68329292