



General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Silver
Year of manufacture	2010
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-01-17
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 1

Date	2021-12-09
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-08
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	60
Total items failed	11

MOT #18 2023-08-09 13:13

MOT test number 694927042829

Result ✓ Passed

Next expiry date 2024-08-08

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated both n/s and o/s (5.3.4 (b) (i))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both n/s and o/s wishbone rear bushes (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both n/s and o/s inner edges (5.2.3 (e))

Advice Offside Front Body component slightly loose bumper (6.2.1 (a) (i))

MOT #17 2023-08-07 15:45

MOT test number 190696513693

Result ✗ Failed

Advice Offside Front Body component slightly loose bumper (6.2.1 (a) (i))

MAJOR Rear Lower Suspension arm corroded and seriously weakened both n/s and o/s (5.3.3 (b) (i))

Minor Front Lower Suspension arm ball joint dust cover severely deteriorated both n/s and o/s (5.3.4 (b) (i))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both n/s and o/s wishbone rear bushes (5.3.4 (a) (i))

Advice Front Tyre worn close to legal limit/worn on edge both n/s and o/s inner edges (5.2.3 (e))

**MOT #16** 2022-07-21 09:48**MOT test number** 430312318740**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))
- Advice** Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security hole under body (6.2.2 (d) (i))
- Advice** Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material in parts front to rear (1.1.11 (c))

MOT #15 2021-07-21 15:37**MOT test number** 347886948197**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear parking brake low effort
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Valve stem slightly damaged slight perished and cracking (5.2.3 (j))

**MOT #14** 2021-07-21 15:37**MOT test number** 582026254440**Result** ✗ Failed

- Advice** Offside Rear parking brake low effort
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Front Valve stem slightly damaged slight perished and cracking (5.2.3 (j))

MOT #13 2020-07-29 13:18**MOT test number** 606797984828**Result** ✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #12**

2020-07-27 12:51

MOT test number

768166641254

Result**✗ Failed****Advice** Offside Front Seat belt slightly damaged Slightly frayed. (7.1.2 (b) (i))**MAJOR** Nearside Front Body component insecure NSF mirror cover insecure. (6.2.1 (a) (i))**MAJOR** Offside Rear Coil spring fractured or broken Broken. (5.3.1 (b) (i))**Advice** NSF and OSR tyre valves perished.**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Corrosion at front and rear brake disc surfaces. (1.1.14 (a) (ii))**MAJOR** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Pass with rectification** Headlamp aim too high NSF and OSF (4.1.2 (a))**Advice** Corrosion at rear subframe.**MOT #11**

2019-07-30 09:31

MOT test number

216477978555

Result**✓ Passed****Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10**

2018-07-23 09:59

MOT test number

466549122023

Result**✓ Passed**

**MOT #9** 2017-07-24 14:50**MOT test number** 877660615341**Result** ✓ Passed**MOT #8** 2017-07-24 11:13**MOT test number** 728224031551**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #7** 2016-07-25 14:01**MOT test number** 441588602297**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #6** 2016-07-25 09:16**MOT test number** 304389408782**Result** ✗ Failed**Advice** Noise from O/S rear when brake applied, possible debris trapped between disc and back plate**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-07-16 10:45**MOT test number** 415227995147**Result** ✓ Passed

**MOT #4** 2014-08-07 08:41**MOT test number** 938129414227**Result** ✓ Passed**Notice** Rear tyres bald inner edge**MOT #3** 2014-08-06 09:31**MOT test number** 259908114207**Result** ✗ Failed**Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Notice** Rear tyres bald inner edge**Fail** Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #2** 2013-07-25 15:59**MOT test number** 607106103280**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Front tyres worn on inside**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in nearside front tyre**Notice** Both rear tyres perished



MOT #1

2013-07-22 16:55

MOT test number

296673403253

Result

✗ Failed

Fail Offside Rear Seat belt affected by an insecure seat fixing (5.2.1b)

Notice Front tyres worn on inside

Advice Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Rear Seat belt affected by an insecure seat fixing (5.2.1b)

Notice Both rear tyres perished

Fail Offside Rear coil spring broken (2.4.C.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Notice Nail in nearside front tyre



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ST10PZH
Plate since	2019-06-29
Current registration	 ST10PZH
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-07-09
Last registration	2023-08-09
Complete history	See info



Registration #1	2010-07-09	14 mi
Registration #2	2013-07-22	48.411 mi
Registration #3	2013-07-25	48.411 mi
Registration #4	2014-08-06	58.721 mi
Registration #5	2014-08-07	58.721 mi
Registration #6	2015-07-16	68.101 mi
Registration #7	2016-07-25	80.951 mi
Registration #8	2016-07-25	80.951 mi
Registration #9	2017-07-24	90.138 mi
Registration #10	2017-07-24	90.142 mi
Registration #11	2018-07-23	96.766 mi
Registration #12	2019-07-22	103.390 mi
Registration #13	2020-07-21	110.014 mi
Registration #14	2021-07-20	116.638 mi
Registration #15	2022-07-19	123.262 mi
Registration #16	2023-07-18	129.886 mi
Registration #17	2024-07-17	136.510 mi
Registration #18	2025-07-16	143.134 mi
Registration #19	2026-07-15	149.758 mi
Registration #20	2027-07-14	156.382 mi
Registration #21	2028-07-13	163.006 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C99289